

Designation: D7240 - 06 (Reapproved 2011)

Standard Practice for Leak Location using Geomembranes with an Insulating Layer in Intimate Contact with a Conductive Layer via Electrical Capacitance Technique (Conductive Geomembrane Spark Test)¹

This standard is issued under the fixed designation D7240; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ε) indicates an editorial change since the last revision or reapproval.

1. Scope

- 1.1 This standard is a performance-based practice for using the spark test to electrically locate leaks in exposed geomembranes with an insulating layer that are in intimate contact with a conductive layer. For clarity, this document uses the term 'leak' to mean holes, punctures, tears, cuts, cracks and similar breaches over the partial or entire area of an installed geomembrane (as defined in 3.2.3).
- 1.2 This test method can be used on exposed geomembranes installed in basins, ponds, tanks, ore and waste pads, landfill cells, landfill caps, and other containment facilities. This standard is applicable for geomembranes in direct and intimate contact with a conductive surface or with a conductive layer integrally included.
- 1.3 **SAFETY WARNING:** The electrical methods used for geomembrane leak location use high voltage, low current power supplies, resulting in the potential for electrical shock. The electrical methods used for geomembrane leak location should be attempted by only qualified and experienced personnel. Appropriate safety measures must be taken to protect the leak location operators as well as other people at the site.
- 1.4 This standard does not purport to address all of the safety and liability concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.

2. Referenced Documents

2.1 *ASTM Standards*:² D4439 Terminology for Geosynthetics

D6747 Guide for Selection of Techniques for Electrical Detection of Leaks in Geomembranes

3. Terminology

- 3.1 Definition of terms applying to this test method appear in Terminology D4439.
 - 3.2 Definitions:
- 3.2.1 *electrical leak location*, *n*—a method which uses electrical current or electrical potential to detect and locate leaks.
- 3.2.2 *geomembrane*, *n*—an essentially impermeable membrane used with foundation, soil, rock, earth or any other geotechnical engineering related material as an integral part of a man made project, structure, or system.
- 3.2.3 *leak*, *n*—For the purposes of this document, a leak is any unintended opening, perforation, breach, slit, tear, puncture or crack. Significant amounts of liquids or solids may or may not flow through a leak. Scratches, gouges, dents, or other aberrations that do not completely penetrate the geomembrane are not considered to be leaks.

Leaks detected during surveys have been grouped into three categories:

- Holes round shaped voids with downward or upward protruding rims
 - Tears linear or circular voids with irregular edge borders
 - Linear cuts linear voids with neat close edges
- 3.2.4 *intimate contact*, *n*—for the purposes of this document, intimate contact is when a conductive layer is in direct contact with the insulating geomembrane, and there are no gaps between the two layers to prohibit the flow of current.
- 3.2.5 leak detection sensitivity, n—The smallest size leak that the leak location equipment and survey methodology are capable of detecting under a given set of conditions. The leak detection sensitivity specification is usually stated as a diameter of the smallest leak that can be reliably detected.
- 3.2.6 *wand*, *n*—for the purposes of this document, any rod that has a conductive brush that is attached to a power source to initiate the spark test.

¹ This practice is under the jurisdiction of ASTM Committee D35 on Geosynthetics and is the direct responsibility of Subcommittee D35.10 on Geomembranes. Current edition approved June 1, 2011. Published July 2011 Originally published in 2006. Last previous edition approved 2006 as D7240–06. DOI: 10.1520/D7240-


² For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

4. Summary of Practice

4.1 The principle of this electrical leak location method is to use a high voltage pulsed power supply to charge a capacitor formed by the underlying conductive layer, the non-conductive layer of the geomembrane and a coupling pad. The area is then swept with a test wand to locate points where the capacitor discharges through a leak. Once the system senses the discharge current, it is converted into an audible alarm.

4.2.1 Fig. 1 shows a wiring diagram of the coupling pad, power supply and test wand for the electrical leak location method of a geomembrane with a lower conductive layer. Once all necessary connections are made, the pad is placed on the upper surface of the geomembrane. The nonconductive (insulating layer(s)) of the geomembrane act as a dielectric in a capacitor which stores electrical potential across the geomembrane.

4.2 General Principles



Legend For Spark Tester Diagram

- 1. Ground Terminal
- 2. High Voltage Terminal
- 3. Sensitivity Dial
- 4. Voltage Dial ($\# \times 1,000 = \text{Wand Voltage}$)
- 5. Voltage Adjusting Screw (Remove plug first) 11. Wand
- 6. Main Power Switches

- 7. Alarm Buzzer
- 8. Ground Lead
- 9. Electrically Conductive Grounding Pad
- High Voltage Lead

FIG. 1 Wiring Diagram of the Equipment Required for Spark Testing Geomembrane in Intimate Contact With a Conductive Surface.

- 4.2.2 A grid, test lanes or other acceptable system should be used to ensure that the entire area is tested with the test wand.
- 4.2.3 Either a hand held wand or a larger wand mounted to an all terrain vehicle may be used. Generally a hand held wand is a more efficient method unless the area is quite large and flat.
 - 4.3 Preparations and Measurement Considerations
- 4.3.1 Testing must be performed on geomembranes that are clean and dry. For geomembrane covered by water or soils, other test procedures, such as described in Guide D6747 will have to be used for testing the geomembrane.
- 4.3.2 Fusion and extrusion welds must be tested using state of the practice nondestructive methods such as air channel test and vacuum box test, respectively. If the test wand gets too close to the edge of the conductive geomembrane, the electrical charge can arc to the back side of the conductive geomembrane and may cause a false positive.

5. Significance and Use

- 5.1 Geomembranes are used as barriers to prevent liquids from leaking from landfills, ponds, and other containments. For this purpose, it is desirable that the geomembrane have as little leakage as practical.
- 5.2 The liquids may contain contaminants that if released can cause damage to the environment. Leaking liquids can erode the subgrade, causing further damage. Leakage can result in product loss or otherwise prevent the installation from performing its intended containment purpose.
- 5.3 Geomembranes are often assembled in the field, either by unrolling and welding panels of the geomembrane material together in the field, or unfolding smaller flexible geomembranes in the field.
- 5.4 In exposed geomembrane applications, geomembrane leaks can be caused by poor quality of the subgrade, accidents, poor workmanship, and carelessness.
- 5.5 Electrical leak location methods are an effective final quality assurance measure to locate previously undetected leaks.

6. Procedure

- 6.1 Before beginning a leak survey, the equipment must be checked to ensure it is in working order. The power source should have a range of voltage from 15,000 to 35,000 volts. A wider voltage range is acceptable but the maximum is typically 35,000 volts. The test wand may be up to 6 feet wide with a brass brush. The coupling pad should be connected as shown in Fig. 1.
- 6.2 Once the equipment has been checked and wired properly, a trial test must be performed. A puncture (deliberate defect) should be introduced in a test piece of geomembrane. The deliberate defect should be approximately 1 mm in diameter. The test piece of geomembrane must be of sufficient size to enable movement of the brush at normal testing speed

over the deliberate defect without touching the edges of the test piece or the coupling pad.

- 6.3 Place the test piece on a large scrap of geomembrane or on the installed geomembrane with the conductive side down. The deliberate defect and the coupling pad should both be on the large scrap piece of geomembrane.
- 6.3.1 Turn on the test unit and adjust the voltage and sensitivity to maximum settings.
- 6.3.2 Sweep the test piece with the wand ensuring that the test wand remains in contact with the geomembrane surface. It is important this be done at normal speeds.
- 6.3.3 Ensure the audible alarm sounds when the brush passes over the deliberate defect. If the alarm does not sound, recheck the connections and retest. If the alarm sounds prior to passing over the damage, turn the sensitivity down and retest the area. The minimum voltage required is site specific and will vary with atmospheric and other site conditions.
- 6.3.4 At a minimum, the equipment should be checked before testing begins and after any shut down of an hour or more. In the event a test reveals the equipment is not working properly, the entire area spark tested since the last passing check of the equipment will have to be retested to assure it was spark tested with working equipment.
- 6.4 Field testing may be performed by marking a predetermined grid, using a two person team or another acceptable method.
- 6.5 The leak location survey shall be conducted using procedures whereby the test wand contacts every point on the surface of the geomembrane being surveyed for leaks neglecting the edge effects.

Note 1—Welded seams cannot be tested using this method. They must be tested by test procedures appropriate for such items – this standard practice applies only to the sections of geomembrane in between the welded edges.


Note 2—Actual survey speed must be no greater than survey speed used during trial test.

7. Reporting

- 7.1 The leak location survey report shall contain the following information
 - Description of the survey site
 - Description of test apparatus
 - Climatic conditions
 - Thickness of geomembrane
 - Survey methodology
 - Results of system functionality and calibration test
 - Location, type and size of leaks
 - Repair technique of detected leaks
 - Map of the surveyed areas

8. Keywords

8.1 geomembrane; leak detection; leak location; electrical leak location method; construction quality assurance



ASTM International takes no position respecting the validity of any patent rights asserted in connection with any item mentioned in this standard. Users of this standard are expressly advised that determination of the validity of any such patent rights, and the risk of infringement of such rights, are entirely their own responsibility.

This standard is subject to revision at any time by the responsible technical committee and must be reviewed every five years and if not revised, either reapproved or withdrawn. Your comments are invited either for revision of this standard or for additional standards and should be addressed to ASTM International Headquarters. Your comments will receive careful consideration at a meeting of the responsible technical committee, which you may attend. If you feel that your comments have not received a fair hearing you should make your views known to the ASTM Committee on Standards, at the address shown below.

This standard is copyrighted by ASTM International, 100 Barr Harbor Drive, PO Box C700, West Conshohocken, PA 19428-2959, United States. Individual reprints (single or multiple copies) of this standard may be obtained by contacting ASTM at the above address or at 610-832-9585 (phone), 610-832-9555 (fax), or service@astm.org (e-mail); or through the ASTM website (www.astm.org). Permission rights to photocopy the standard may also be secured from the Copyright Clearance Center, 222 Rosewood Drive, Danvers, MA 01923, Tel: (978) 646-2600; http://www.copyright.com/