

Zinc coatings — Guidelines and recommendations for the protection against corrosion of iron and steel in structures

Part 3: Sherardizing

ICS 25.220.40; 91.080.10

National foreword

This British Standard is the UK implementation of EN ISO 14713-3:2009, incorporating corrigendum March 2010. It is identical to ISO 14713-3:2009. Together with BS EN ISO 14713-1:2009 and BS EN ISO 14713-2:2009, it supersedes BS EN ISO 14713:1999 which is withdrawn.

The UK participation in its preparation was entrusted to Technical Committee STI/34, Hot dip galvanized coatings.

A list of organizations represented on this committee can be obtained on request to its secretary.

This publication does not purport to include all the necessary provisions of a contract. Users are responsible for its correct application.

Compliance with a British Standard cannot confer immunity from legal obligations.

Amendments/corrigenda issued since publication

Date	Comments
30 April 2010	Implementation of CEN corrigendum March 2010; Supersession details added to EN foreword

This British Standard was published under the authority of the Standards Policy and Strategy Committee on 28 February 2010

© BSI 2010

ISBN 978 0 580 70921 0

English Version

Zinc coatings - Guidelines and recommendations for the
protection against corrosion of iron and steel in structures - Part
3: Sherardizing (ISO 14713-3:2009)

Revêtements de zinc - Lignes directrices et
recommandations pour la protection contre la corrosion du
fer et de l'acier dans les constructions - Partie 3:
Shérardisation (ISO 14713-3:2009)

Zinküberzüge - Leitfäden und Empfehlungen zum Schutz
von Eisen- und Stahlkonstruktionen vor Korrosion - Teil 3:
Sherardisieren (ISO 14713-3:2009)

This European Standard was approved by CEN on 18 November 2009.

CEN members are bound to comply with the CEN/CENELEC Internal Regulations which stipulate the conditions for giving this European Standard the status of a national standard without any alteration. Up-to-date lists and bibliographical references concerning such national standards may be obtained on application to the CEN Management Centre or to any CEN member.

This European Standard exists in three official versions (English, French, German). A version in any other language made by translation under the responsibility of a CEN member into its own language and notified to the CEN Management Centre has the same status as the official versions.

CEN members are the national standards bodies of Austria, Belgium, Bulgaria, Cyprus, Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Romania, Slovakia, Slovenia, Spain, Sweden, Switzerland and United Kingdom.



EUROPEAN COMMITTEE FOR STANDARDIZATION
COMITÉ EUROPÉEN DE NORMALISATION
EUROPÄISCHES KOMITEE FÜR NORMUNG

Management Centre: Avenue Marnix 17, B-1000 Brussels

Foreword

This document (EN ISO 14713-3:2009) has been prepared by Technical Committee ISO/TC 107 "Metallic and other inorganic coatings" in collaboration with Technical Committee CEN/TC 262 "Metallic and other inorganic coatings", the secretariat of which is held by BSI.

This European Standard shall be given the status of a national standard, either by publication of an identical text or by endorsement, at the latest by June 2010, and conflicting national standards shall be withdrawn at the latest by June 2010.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. CEN [and/or CENELEC] shall not be held responsible for identifying any or all such patent rights.

This document supersedes EN ISO 14713:1999.

According to the CEN/CENELEC Internal Regulations, the national standards organizations of the following countries are bound to implement this European Standard: Austria, Belgium, Bulgaria, Cyprus, Czech Republic, Denmark, Estonia, Finland, France, Germany, Greece, Hungary, Iceland, Ireland, Italy, Latvia, Lithuania, Luxembourg, Malta, Netherlands, Norway, Poland, Portugal, Romania, Slovakia, Slovenia, Spain, Sweden, Switzerland and the United Kingdom.

Endorsement notice

The text of ISO 14713-3:2009 has been approved by CEN as a EN ISO 14713-3:2009 without any modification.

Contents

Page

Introduction	iv
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
4 Design for sherardizing	2
4.1 General	2
4.2 Surface preparation	2
4.3 Design considerations	3
4.4 Clearances of threaded components	3
5 Storage and transport	4
5.1 General	4
5.2 Recommendations for storage and transport	4
6 Effects of article condition on quality of sherardizing	4
6.1 Composition	4
6.2 Surface condition	5
6.3 Influence of steel surface roughness on the sherardized coating thickness	5
6.4 Internal stresses in the base material	5
6.5 Large objects and thick steels	6
7 Effect of sherardizing process on the article	6
7.1 Processing circumstances	6
7.2 Coating properties influenced by the sherardizing process	7
8 After-treatments	7
Bibliography	8

Introduction

Sherardizing is a thermal diffusion process in which articles are heated in the presence of a sherardizing mixture consisting of zinc dust with or without an inert material.

The process is carried out in a slowly rotating closed container at temperatures ranging from about 300 °C to 500 °C. The normal processing temperature is below the melting point of zinc (419 °C).

During the process, zinc/iron alloys are built up on the surface of the ferrous articles. A coating thickness of 10 µm to 75 µm (and higher if required) can be achieved. The coating thickness is accurately controlled by the amount of zinc dust, the processing time and temperature. The coating closely follows the contours of the basis material, and uniform coatings are produced on articles, including those of irregular shape.

After sherardizing, the containers are cooled down. A screening process separates the sherardized articles from the unused sherardizing mixture. The articles, with the zinc/iron-alloyed layer, are normally post-treated by phosphating, chromating or another suitable passivation process (conversion coating) resulting in a dust free and clean passivated surface.

Most steel and iron articles can be sherardized.

Zinc coatings — Guidelines and recommendations for the protection against corrosion of iron and steel in structures —

Part 3: Sherardizing

1 Scope

This part of ISO 14713 provides guidelines and recommendations regarding the general principles of design that are appropriate for articles to be sherardized for corrosion protection.

The protection afforded by the sherardized coating to the article will depend upon the method of application of the coating, the design of the article and the specific environment to which the article is exposed. The sherardized article can be further protected by application of additional coatings (outside the scope of this part of ISO 14713), such as organic coatings (wet paints or powder coatings). When applied to sherardized articles, this combination of coatings is often known as a “duplex system”.

General guidance on this subject can be found in ISO 12944-5 and EN 13438.

The maintenance of corrosion protection in service for steel with sherardized coatings is outside the scope of this part of ISO 14713.

Specific product-related requirements (e.g. for sherardized coatings on fasteners or tubes, etc.) will take precedence over these general recommendations.

2 Normative references

The following referenced documents are indispensable for the application of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 8044, *Corrosion of metals and alloys — Basic terms and definitions*

ISO 12944-5, *Paint and varnishes — Corrosion protection of steel structures by protective paint systems — Part 5: Protective paint systems*

ISO 18265, *Metallic materials — Conversion of hardness values*

EN 13811, *Sherardizing — Zinc diffusion coatings on ferrous products — Specification*

3 Terms and definitions

For the purposes of this document, the terms and definitions given in ISO 8044 and the following apply.

3.1 sherardizing
thermal diffusion process in which articles are heated in close contact with a sherardizing mixture, consisting of zinc dust with or without an inert material, in a closed container, usually rotated

3.2 sherardized coating
coating consisting of zinc/iron alloys obtained by the sherardizing process, and normally post-treated by phosphating, chromating or another suitable passivating process (conversion coating)

NOTE "Sherardized coating" is referred to in this part of ISO 14713 as "coating".

4 Design for sherardizing

4.1 General

It is essential that the design of any article required to be finished should take into account not only the function of the article and its method of manufacture but also the limitations imposed by the finish.

Sherardizing is a process developed to protect components of various sizes, but mainly small articles, against corrosion and wear. No jig marks are visible after sherardizing. Normal sherardizing equipment has containers with nominal dimensions of 2 000 mm × 480 mm × 400 mm. Specialized equipment has been developed to treat large tubes for the gas and oil industry, and large articles of complex shape for the automotive industry.

Some internal stresses in the articles to be sherardized will be relieved during the sherardizing process and this may cause deformation of the coated article. Normally, the sherardizing is carried out between 320 °C and 419 °C.

The purchaser should seek the advice of the sherardizer before designing or manufacturing a product that is subsequently to be sherardized, as it may be necessary to adapt the construction of the article for the sherardizing process, especially when very fragile components are sent for sherardizing. These components may be liable to damage and distortion during processing. The sherardizer may be able to recommend a design modification.

4.2 Surface preparation

The design and the materials used should permit good surface preparation. This is essential for the production of a high-quality coating. Sherardizing is only effective on surfaces free of oil, grease, and rust, scale or other surface contaminants. It is recommended to avoid lacquers, wax, paint, oil and grease-based markings. Surfaces should be free from defects to ensure a coating of good appearance and serviceability.

Grit blasting is the preferred surface preparation for sherardizing, because

- the abraded surface responds very well to the sherardizing process, and
- the risk of hydrogen embrittlement to spring steels and to high-tensile steels, or damage to free-cutting steels, is avoided.

In case alkaline degreasing is applied, the articles should be dried before being grit blasted, if necessary, or before being sherardized.

Sintered materials should be free of oil and resins before they are sent for sherardizing.

For castings, grit blasting is essential to remove moulding sand.

In special cases, e.g. to remove scale, hydrochloric acid pickling can be considered. However, it is recommended to remove scale from articles before the final machining, so that the articles are not damaged in the pretreatment stage of the sherardizing process to provide a coating of good appearance and serviceability. The purchaser should seek the advice of the sherardizer in case such a pretreatment is required.

4.3 Design considerations

Articles to be sherardized are limited in size, since most of the containers used in the sherardizing process have nominal dimensions of 2 000 mm × 480 mm × 400 mm. Articles that are too large for such a container cannot be sherardized partially. When jointed assemblies or fabrications (not welded assemblies) have dimensions larger than the dimensions of the sherardizing containers, it should be considered to sherardize the unassembled parts and assemble the parts after sherardizing.

Internal threads or recesses can be cut before the articles are sent for sherardizing. The uniform zinc alloy layers closely follow the contours of the articles to be sherardized. Tubes and hollow articles can be sherardized. Special measures, for example prefilling the hollow sections with the sherardizing mixture, can be taken to ensure that the inside of these products is coated as well.

Springs and high-tensile steels are also suitable for sherardizing. To prevent affecting the integrating properties of such articles, the sherardizing should be carried out at appropriate temperatures, depending on the hardening and tempering temperatures of these articles. Springs should preferably be sherardized unassembled in a free and unloaded state. Depending on the heat treatment of these articles before finishing, the sherardizing can be carried out at lower temperatures between 320 °C and 380 °C. The processing time, however, will be extended when sherardizing at lower temperatures.

Articles having soft-soldered or resin-bonded joints should not be sent for sherardizing, as joints of this nature are effected by the sherardizing process.

Welding is preferable before sherardizing. All welds should be free of slag. Spot welding is possible after the articles are sherardized; ideally, thinner coatings, less than 15 µm in thickness, are desired.

On mating surfaces and holes, extra clearance should be provided to allow for the thickness of the coating material specified (see EN 13811).

For the clearance recommendations for threaded components, see 4.4.

4.4 Clearances of threaded components

Although sherardizing gives a uniform coating without any significant changes in the profile of threads, there must be adequate clearance between external and internal threads before sherardizing.

The recommended clearances are given in Table 1.

Table 1 — Clearances recommended for bolts and nuts to be sherardized

Minimum coating thickness µm	Coating class according to EN 13811	ISO metric, UNF and UNC threads µm
15	Class 15	180
30	Class 30	360
45	Class 45	540

If only the external thread is to be sherardized and then used with a standard uncoated internal thread (or *vice versa*) then half the clearance shown in Table 1 is required on the thread to be sherardized.

It is recommended to sherardize both bolts and nuts. Whenever possible, nuts and bolts sent for sherardizing should be forwarded to the sherardizer together, so that the clearance can be checked.

General practice for threaded bolts and nuts to be sherardized is either of the following:

- a) the bolts are manufactured to the tolerances laid down in the appropriate specifications, without allowance being made for sherardizing; the nuts are then tapped up to the oversize mentioned in Table 1, before sherardizing; or
- b) the bolts are oversized to a level mentioned in Table 1, so that standard threads on sherardized nuts can be used in all cases.

A coating thickness of 10 µm is recommended for small threaded articles of dimensions less than M10.

The purchaser should seek the advice of the sherardizer before designing or manufacturing threaded materials to be sherardized.

5 Storage and transport

5.1 General

The coating has a matt grey appearance, the natural colour of the zinc/iron alloy layer of the surface after sherardizing, and is normally post-treated by phosphating, chromating or another suitable passivation process (conversion coating). This prevents wet-storage stains on the coating, so-called "white rust", during storage in humid conditions or during transport, and increases the life time in service.

Due to the zinc/iron alloy composition of the coating, it may acquire, during outside exposure, a dark orange-brown patina. This is not to be confused with corrosion of the base material, but results from the initial colour change of the zinc/iron alloy by normal oxidation when exposed to humid conditions outside.

This discolouration is not detrimental to the coating properties and the use of the coated article. On continued exposure, the surface becomes darker in colour and the coating has a normal life depending on the coating thickness.

5.2 Recommendations for storage and transport

If possible, sherardized tubes and other hollow articles should be stored vertically and loosely pending the use, thus preventing water or any other corrosive fluids from being trapped. Bulk articles should be stored in dry conditions. Special care should be taken to store (large) threaded materials to avoid damaging the threads.

Outdoor transport of bulk articles should be carried out in dry conditions, if possible in (closed) containers or bags.

6 Effects of article condition on quality of sherardizing

6.1 Composition

Unalloyed carbon steels, low-alloy steels, sintered materials, and malleable grey and cast iron are suitable for sherardizing. Spring steel and high-tensile steel can be satisfactorily sherardized. Depending on the hardening and tempering temperature of these parts, the sherardizing process is carried out at appropriate temperatures, ranging from 320 °C to 380 °C.

The chemical composition of the steel has no practical influence on the composition, or on the thickness of the coating.

6.2 Surface condition

The surface of the base material should be clean before sherardizing.

Surface contamination that cannot be removed by grit blasting should be removed prior to the mechanical pretreatment process. The responsibility of removing the contamination should be agreed between the sherardizer and purchaser.

6.3 Influence of steel surface roughness on the sherardized coating thickness

Surface roughness has no practicable influence on the sherardized coating structure or the properties of the coating.

It is recommended that flame-cut, laser-cut and plasma-cut surfaces should be ground off by the fabricator.

6.4 Internal stresses in the base material

6.4.1 General

The sherardizing process can be carried out at temperatures ranging from 300 °C to 500 °C. The articles to be sherardized are slowly heated up to the processing temperature, normally below 419 °C. The processing time will be approximately 1 h to 2 h to form the coating by thermal diffusion. After sherardizing, the articles are cooled down slowly to room temperature.

This processing does not cause internal stresses in the base material, except for steels that have tempering temperatures that fall within the processing temperature range.

For these steels, it is necessary to carry out the sherardizing process at the lower end of the processing temperature range (320 °C to 380 °C). However, for steels with a tempering temperature below 320 °C, it is hard to sherardize without affecting the properties of these steels.

The sherardizer cannot be responsible for deformation of the steel work during sherardizing (as the specific state of stress in the article at the time of processing is not within his control) unless the distortion has occurred through faulty processing.

6.4.2 Distortion cracking

Hardened and/or high-tensile steels may contain internal stresses of such a magnitude that sherardizing may increase the risk of cracking of the steel during sherardizing. The risk of cracking can be reduced by sherardizing at lower temperatures and/or by stress relieving before sherardizing. Specialist advice should be sought when sherardizing such steels.

NOTE High-tensile steels feature a yield strength greater than or equal to 650 MPa.

A stress-relieving heat treatment should be planned at the design stage and should be executed at the fabrication stage subsequently to cold-working welding, oxy-cutting or drilling. The reduction of the residual stresses, inherently associated with cold forming, may be obtained with a stress-relieving heat treatment, typically at 600 °C.

However, if 600 °C is significantly exceeded due to poor control of the thermal cycle, a lowering of the mechanical properties of steel might be observed. Therefore, stress-relieving heat treatments should be based on a specialist's advice.

Residual stresses and hardening are created in the welded areas or the areas affected by oxy-cutting. Their magnitude depends on different factors, for example, length and thickness of welds and welding procedures.

Residual stresses and hardening in the fabricated element may be responsible for damage or deformation of the coated article. Therefore, residual stresses and hardening must be minimized by adequate design and welding procedures. Critical constructional details may be subjected to an additional heat treatment for stress-relief. Similar recommendations may also be followed for drilling and stamping processes.

6.4.3 Hydrogen embrittlement

Structural steels are not normally embrittled by the absorption of hydrogen during pickling, and if there is any hydrogen remaining, it does not, in general, affect structural steels.

If steels are harder than approximately 34 HRC, 340 HV or 325 HB (see ISO 18265), care is necessary to minimize hydrogen absorption during surface preparation by pickling with hydrochloric acid. The welds and the heat-affected zones (HAZ) of structural steels do not normally exceed a hardness value of 340 HV. Therefore, these zones should not normally be embrittled by the absorption of hydrogen during surface preparation.

During sherardizing, the articles are slowly heated up to the processing temperature (normally between 320 °C and 419 °C). The eventually absorbed hydrogen is available for discharge before the coating layer has developed.

6.5 Large objects and thick steels

The thickness and dimensions of the steel articles have no effect on the development of the coating, the coating composition and the properties of the coating.

7 Effect of sherardizing process on the article

7.1 Processing circumstances

The coating follows very closely the contours of the article to be sherardized. However, for threaded components, a clearance allowance should be made on mating threads to accommodate the thickness of the coating. The recommended clearances are given in Table 1.

High-tensile steel articles, such as bolts and nuts up to class 12.9, are suitable for sherardizing. Special care should be taken for such products in the pretreatment process. The purchaser should seek the advice of the sherardizer in case such parts are sent for sherardizing.

Sherardizing does not give rise to hydrogen embrittlement (6.4.3), or liquid metal assisted cracking LMAC (liquid metal embrittlement LME), as the process is a dry thermal diffusion process and the steel articles are normally not in contact with molten zinc when sherardizing takes place below 419 °C.

Materials that will be adversely affected by the heat of the sherardizing process should not be sherardized. For steels whose tempering temperature falls in the processing temperature range of 300 °C to 500 °C, it is necessary to carry out the sherardizing process at the lower end of the processing temperature range. However, for steels with a tempering temperature below 320 °C, it is hard to sherardize these steels without affecting the properties (see 6.4.1).

Heat treated or cold-worked steels may be tempered by the heat in the sherardizing process and lose some of any increased strength obtained by heat treatment or cold working. The purchaser should seek the advice of the sherardizer, in case such parts are sent for sherardizing.

7.2 Coating properties influenced by the sherardizing process

7.2.1 Sherardizing practice

Small additions to the sherardizing mixture can be used, as part of the processing technique of sherardizers, to improve the coating quality.

7.2.2 Surface properties of the finished article

The sherardized surface is built up of zinc/iron alloys containing mainly zinc. The surface shows a certain roughness. Due to the iron content of the surface alloy layer, the coating derives a special property, abrasion resistance and high hardness, typically 350 HV, enabling it to withstand mechanical abrasion and rough handling. Sherardizing is, in particular, used to finish, for example, scaffolding fittings, nails and chains.

The rather rough passivated surface is a good surface for paint and organic powder coating adhesion, as well as for rubber or rubber-like bonded steel components.

8 After-treatments

To minimize the possible formation of wet-storage stains on the surface, the coating can be post-treated, by means of phosphating, chromating or another suitable passivation process (conversion coating) as part of the sherardizing process.

Sherardized articles might be treated with a lubricant to regulate the coefficient of friction of the surface. This is used to great effect on threaded articles and hinge pins.

If the articles are to be painted or powder coated after sherardizing (duplex systems), the purchaser should inform the sherardizer before the article is sherardized. In most cases, no pretreatment of the sherardized surface is needed before painting or powder coating.

Proprietary products are available for preparation of sherardized coatings for painting or powder coating.

For the application of duplex systems involving the use of paints, requirements on surface treatment, painting systems, coating thickness, application technologies, etc., have to be defined by agreement between the customer and the purchaser. More information is given in ISO 12944-5.

For the application of duplex systems involving the use of powder coatings, recommendations on coating powders, pretreatments, application and system performance can be found in EN 13438 and EN 15773.

Bibliography

- [1] EN 13438, *Paints and varnishes — Powder organic coatings for galvanized or sherardized steel products for construction purposes*
- [2] EN 15773, *Industrial application of powder organic coatings to hot dip galvanized or sherardized steel articles [duplex systems] — Specifications, recommendations and guidelines*
- [3] PORTER, FRANK, *Zinc Handbook*, Chapter 16, Marcel Dekker Inc. 1991

BSI - British Standards Institution

BSI is the independent national body responsible for preparing British Standards. It presents the UK view on standards in Europe and at the international level. It is incorporated by Royal Charter.

Revisions

British Standards are updated by amendment or revision. Users of British Standards should make sure that they possess the latest amendments or editions.

It is the constant aim of BSI to improve the quality of our products and services. We would be grateful if anyone finding an inaccuracy or ambiguity while using this British Standard would inform the Secretary of the technical committee responsible, the identity of which can be found on the inside front cover. Tel: +44 (0)20 8996 9000. Fax: +44 (0)20 8996 7400.

BSI offers members an individual updating service called PLUS which ensures that subscribers automatically receive the latest editions of standards.

Buying standards

Orders for all BSI, international and foreign standards publications should be addressed to Customer Services. Tel: +44 (0)20 8996 9001. Fax: +44 (0)20 8996 7001 Email: orders@bsigroup.com You may also buy directly using a debit/credit card from the BSI Shop on the Website <http://www.bsigroup.com/shop>

In response to orders for international standards, it is BSI policy to supply the BSI implementation of those that have been published as British Standards, unless otherwise requested.

Information on standards

BSI provides a wide range of information on national, European and international standards through its Library and its Technical Help to Exporters Service. Various BSI electronic information services are also available which give details on all its products and services. Contact Information Centre. Tel: +44 (0)20 8996 7111 Fax: +44 (0)20 8996 7048 Email: info@bsigroup.com

Subscribing members of BSI are kept up to date with standards developments and receive substantial discounts on the purchase price of standards. For details of these and other benefits contact Membership Administration. Tel: +44 (0)20 8996 7002 Fax: +44 (0)20 8996 7001 Email: membership@bsigroup.com

Information regarding online access to British Standards via British Standards Online can be found at <http://www.bsigroup.com/BSOL>

Further information about BSI is available on the BSI website at <http://www.bsigroup.com>

Copyright

Copyright subsists in all BSI publications. BSI also holds the copyright, in the UK, of the publications of the international standardization bodies. Except as permitted under the Copyright, Designs and Patents Act 1988 no extract may be reproduced, stored in a retrieval system or transmitted in any form or by any means – electronic, photocopying, recording or otherwise – without prior written permission from BSI.

This does not preclude the free use, in the course of implementing the standard, of necessary details such as symbols, and size, type or grade designations. If these details are to be used for any other purpose than implementation then the prior written permission of BSI must be obtained.

Details and advice can be obtained from the Copyright and Licensing Manager. Tel: +44 (0)20 8996 7070 Email: copyright@bsigroup.com