
Plastics — Determination of ash —
Part 1:
General methods

Plastiques — Détermination du taux de cendres —
Partie 1: Méthodes générales



PDF disclaimer

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below.



COPYRIGHT PROTECTED DOCUMENT

© ISO 2008

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents

Page

Foreword	iv
1 Scope	1
2 Normative references	1
3 Terms and definitions	1
4 Principle	2
5 Reagents (for methods B and C only)	2
6 Apparatus	2
7 Procedure	3
7.1 Test portion	3
7.2 Test conditions	3
7.3 Method A — Direct calcination	4
7.4 Method B — Calcination following sulfuric acid treatment after burning	4
7.5 Method C — Calcination following sulfuric acid treatment before burning	5
8 Number of tests	5
9 Expression of results	5
10 Precision	5
11 Test report	6

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

International Standards are drafted in accordance with the rules given in the ISO/IEC Directives, Part 2.

The main task of technical committees is to prepare International Standards. Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights.

ISO 3451-1 was prepared by Technical Committee ISO/TC 61, *Plastics*, Subcommittee SC 5, *Physical-chemical properties*.

This fourth edition cancels and replaces the third edition (ISO 3451-1:1997), which has been technically revised, in particular with respect to the mass of the test portion used (see 7.1).

ISO 3451 consists of the following parts, under the general title *Plastics — Determination of ash*:

- *Part 1: General methods*
- *Part 2: Poly(alkylene terephthalate) materials*
- *Part 3: Unplasticized cellulose acetate*
- *Part 4: Polyamides*
- *Part 5: Poly(vinyl chloride)*

Plastics — Determination of ash —

Part 1: General methods

SAFETY STATEMENT — Persons using this document should be familiar with normal laboratory practice, if applicable. This document does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user to establish appropriate safety and health practices and to ensure compliance with any regulatory requirements.

1 Scope

This part of ISO 3451 specifies general methods, with suitable test conditions, for the determination of the ash of a range of plastics (resins and compounds). The particular conditions chosen may be included in the specifications for the plastic material in question.

Particular conditions applicable to poly(alkylene terephthalate) materials, unplasticized cellulose acetate, polyamides and poly(vinyl chloride) plastics, including some specific filled, glass-fibre-reinforced and flame-retarded materials, are specified in ISO 3451-2, ISO 3451-3, ISO 3451-4 and ISO 3451-5.

2 Normative references

The following referenced documents are indispensable for the application of this document. For dated references, only the edition cited applies. For undated references, the latest edition of the referenced document (including any amendments) applies.

ISO 472, *Plastics — Vocabulary*

3 Terms and definitions

For the purposes of this document, the terms and definitions given in ISO 472 apply.

4 Principle

It is possible to determine the ash of an organic material by three main methods:

- a) Direct calcination, i.e. by burning the organic matter and heating the residue at high temperature until constant mass is reached (method A).
- b) Calcination after sulfation, which may be carried out by two different procedures:
 - With sulfuric acid treatment after burning, i.e. by burning the organic matter, transforming the inorganic residue into sulfates with concentrated sulfuric acid and heating the residue at high temperature until constant mass is reached. This is the common method of obtaining “sulfated ash” (method B).
 - With sulfuric acid treatment before burning, i.e. by heating the organic matter together with concentrated sulfuric acid up to temperatures where fuming and subsequent burning of the organic matter occur, and finally heating the residue at high temperature until constant mass is reached (method C). This procedure may be used if volatile metal halides are liable to evaporate during burning of the organic matter. It is not applicable to silicones or fluorine-containing polymers.

In each case, the final step of the procedure is calcination at 600 °C, 750 °C, 850 °C or 950 °C until constant mass is reached (see 7.2).

NOTE The mass of the ash may vary with the temperature of ignition. For example, higher temperatures such as 850 °C will convert calcium carbonate and other carbonates to their oxides and thus give lower values for the ash.

5 Reagents (for methods B and C only)

During the analysis, use only reagents of analytical grade and only distilled water or water of equivalent purity.

- 5.1 **Ammonium carbonate**, anhydrous.
- 5.2 **Ammonium nitrate**, approximately 10 % (by mass) solution.
- 5.3 **Sulfuric acid**, $\rho = 1,84 \text{ g/cm}^3$.

WARNING — Highly corrosive. Handle with suitable skin and eye protection in a fume cupboard. Reacts exothermically with water.

- 5.4 **Sulfuric acid**, 50 % (by volume) solution.

WARNING — Handle with care. Prepare by slowly adding the concentrated acid to water.

6 Apparatus

- 6.1 **Crucible**, made of silica, porcelain or platinum, inert to the material tested. The use of a crucible lid/watch-glass may be beneficial for samples producing a fine particulate ash.
- 6.2 **Gas burner**, or other appropriate heat source.
- 6.3 **Muffle furnace** or **microwave furnace**, capable of being maintained at 600 °C ± 25 °C, 750 °C ± 50 °C, 850 °C ± 50 °C or 950 °C ± 50 °C, as appropriate.
- 6.4 **Analytical balance**, accurate to 0,1 mg.
- 6.5 **Pipettes**, of suitable capacity (for methods B and C only).

6.6 Desiccator, containing an efficient desiccant which does not interact with the ash.

NOTE In certain cases, the ash may have a greater affinity for water than some substances commonly used as desiccants.

6.7 Weighing bottle.

6.8 Fume cupboard.

7 Procedure

7.1 Test portion

Take a quantity of the test sample sufficient to yield 5 mg to 500 mg of ash (see Table 1). In the case of reinforced materials, take a test portion of 2 g. If the likely quantity of ash is unknown, carry out a preliminary ash determination. Depending on the approximate ash content, choose the size of the test portion to be used from Table 1.

Table 1 — Mass of test portion

Approximate ash %	Test portion g	Mass of ash obtained mg
≤ 0,01	≥ 200	approximately 5 to 10
> 0,01 to 0,05	100	10 to 50
> 0,05 to 0,1	50	25 to 50
> 0,1 to 0,2	25	25 to 50
> 0,2 to 1	10	20 to 100
> 1 to 10	5	50 to 500
> 10	2	200

For plastics yielding very low ash, it is necessary to use larger test portions. When it is impossible to burn the whole of the test portion at one time, weigh the required quantity in a suitable weighing bottle and introduce it into the crucible (6.1) in convenient amounts for a succession of burnings until the whole of the test portion has been burnt.

7.2 Test conditions

Calcination shall be continued to constant mass as defined in 7.3.6, but the duration of the calcination in the muffle furnace (6.3) shall not exceed 3 h at the specified temperature.

The choice of the calcination temperature and the use of the sulfation method depend on the nature of the plastic and any additives it may contain. If a choice exists between different satisfactory conditions, choose those that allow the attainment of constant mass in less than 3 h. A higher temperature or the use of sulfation generally shortens the duration of the calcination.

Whichever method — A, B or C — is used, choose one of the following temperature ranges for the final (calcination) step, unless other temperatures are requested for special technical or commercial reasons:

600 °C ± 25 °C, 750 °C ± 50 °C, 850 °C ± 50 °C, 950 °C ± 50 °C.

Use a fume cupboard for the ashing procedure.

For method A, if it can be conclusively demonstrated for a particular sample type that direct ashing in a muffle furnace without preheating/igniting the sample over a Bunsen flame or equivalent gives the same result, then this version of method A (rapid ashing) is permitted. The use of this rapid ashing method shall be included in the test report.

7.3 Method A — Direct calcination

7.3.1 Prepare the crucible (6.1) by heating it in the muffle furnace (6.3) at the test temperature until constant mass is reached. Allow to cool in the desiccator (6.6) to room temperature for 1 h, or until room temperature is reached, and weigh on the analytical balance (6.4) to the nearest 0,1 mg.

7.3.2 Introduce into the tared weighing bottle (6.7) a test portion (pre-dried as described in the corresponding material specification) of mass in accordance with Table 1. Weigh again to the nearest 0,1 mg or to 0,1 % of the mass of the test portion. If the test portion corresponding to the amount of ash specified in Table 1 does not more than half fill the crucible, this quantity may be placed directly into the crucible and weighed in it. The procedure described below assumes that this will not be the case, however. High-bulk materials may be compressed into tablets, which may then be broken up into fragments of appropriate size.

7.3.3 Introduce into the crucible enough of the test portion to half fill the crucible. Heat the crucible directly on the burner or other suitable heating device (6.2) to burn slowly until volatile products have been driven off. Repeat the operation until the whole test portion is well charred.

7.3.4 Introduce the crucible into the muffle furnace preheated to the prescribed temperature and calcine for 30 min.

7.3.5 Place the crucible in the desiccator, allow it to cool for 1 h, or until room temperature is reached, and weigh on the analytical balance to the nearest 0,1 mg.

7.3.6 Calcine again under the same conditions until constant mass is reached, i.e. until the results of two consecutive weighings do not differ from each other by more than 0,5 mg.

7.3.7 If a laboratory can document that their procedure for time and temperature of a single calcination on a given material results in constant mass, then this so-called "rapid method" shall be permitted and the test report shall note a single calcination. In the event of a dispute, the referee method shall be calcination to constant mass.

7.4 Method B — Calcination following sulfuric acid treatment after burning

7.4.1 Proceed as specified in 7.3.1, 7.3.2 and 7.3.3.

7.4.2 After cooling, add sulfuric acid solution (5.4) drop by drop with a pipette of suitable capacity (6.5) to moisten the residue completely and heat until fuming ceases, avoiding too vigorous boiling.

7.4.3 If traces of carbonaceous materials remain after cooling, add 1 to 5 drops of ammonium nitrate solution (5.2) and heat until the evolution of white fumes ceases completely.

7.4.4 In order to reconvert metal oxides formed during the preceding steps into sulfates, add, after cooling, about 5 drops of concentrated sulfuric acid (5.3) and heat until there is no further evolution of white fumes, avoiding vigorous boiling or the loss of ash by excessive fuming.

7.4.5 After cooling, add 1 g to 2 g of solid ammonium carbonate (5.1) and heat, avoiding loss of ash, until the fuming has ceased. Then place the crucible in the muffle furnace preheated to the indicated temperature and proceed as specified in 7.3.4, 7.3.5 and 7.3.6.

7.5 Method C — Calcination following sulfuric acid treatment before burning

7.5.1 This method shall never be used with silicones or fluorine-containing polymers.

7.5.2 Proceed as specified in 7.3.1 and 7.3.2.

7.5.3 Introduce into the crucible enough of the test portion to half fill the crucible. Add with a pipette (6.5) a sufficient amount of concentrated sulfuric acid (5.3) to moisten the material completely. Cover the crucible with a watch-glass. Heat the crucible directly on the burner over a low flame until the organic material begins to decompose.

Continue heating carefully, adjusting the watch-glass so as to allow the acid to be fumed off and making sure that no ash-containing material is lost. With plastics which have a tendency to lose ash-containing material, it is recommended that the crucible with its contents be placed into a holed board made of fireproof material (e.g. ceramic fibre) and heated with a low flame only so that the organic matter smoulders rather than burns. If the initial charge in the crucible was insufficient to yield an acceptable mass of ash, allow the crucible to cool, add more of the test portion and repeat the operations described above until the whole test portion has been burnt. Remove the watch-glass, making sure that no solid particles are adhering to it.

In cases where the sulfuric acid tends to creep over the lip of the crucible or where, despite precautions, some of the test portion tends to be lost by violent reaction (frequently in the case of PVC), the concentrated sulfuric acid may be replaced by a mixture of concentrated acetic and sulfuric acids. The use of these mixed acids shall be agreed between the interested parties and reference made to it in the test report.

7.5.4 Proceed as specified in 7.4.3, 7.4.4 and 7.4.5.

8 Number of tests

The number of tests and the permissible scatter of results should normally be stated in the particular standard for each material. If such information is not available, carry out two determinations, repeating the test as necessary until the results of two successive determinations do not differ from each other by more than 10 % of their mean.

9 Expression of results

The ash or sulfated ash, expressed as a percentage by mass, is given by the formula

$$\frac{m_1}{m_0} \times 100$$

where

m_0 is the mass, in grams, of the dried test portion;

m_1 is the mass, in grams, of the ash obtained.

10 Precision

Precision data have been determined by collaborative testing involving eight laboratories and eight different materials. The results are summarized in Table 2.

Table 2 — Summary of precision data

Material/filler	Mean ash %	s_r	s_R	r	R
HDPE/antiblock	0,015	0,004	0,005	0,011	0,015
LDPE/antiblock	0,149	0,005	0,005	0,013	0,015
LDPE/antiblock	0,437	0,005	0,006	0,013	0,017
LDPE/antiblock	1,00	0,009	0,009	0,025	0,025
PET/SiO ₂	3,18	0,045	0,045	0,125	0,125
PET/TiO ₂	12,46	0,046	0,052	0,129	0,144
PA/glass	33,16	0,272	0,282	0,760	0,790
PET/TiO ₂	44,81	0,371	0,400	1,038	1,120

s_r is the repeatability standard deviation.
 s_R is the reproducibility standard deviation.
 r is the repeatability limit, i.e. the value below which the absolute difference between two single test results obtained under repeatability conditions (same operator, same apparatus, same laboratory and within a short interval of time) may be expected to lie with a probability of 95 %.
 R is the reproducibility limit, i.e. the value below which the absolute difference between two single test results obtained under reproducibility conditions (different operators, different apparatus and different laboratories) may be expected to lie with a probability of 95 %.

11 Test report

The test report shall include the following particulars:

- a) a reference to this part of ISO 3451;
- b) all details necessary for complete identification of the material tested;
- c) the method used [A, A (rapid ashing), B or C] and, if the acetic and sulfuric acid mixture was used, a statement to this effect (see 7.5.3, last paragraph);
- d) the calcining temperature used;
- e) the number of test portions used, and the mass of each;
- f) the results and their scatter;
- g) the date of the determination.

