

Standard Test Methods for Thin Thermally Conductive Solid Materials for Electrical Insulation and Dielectric Applications¹

This standard is issued under the fixed designation D6343; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ε) indicates an editorial change since the last revision or reapproval.

1. Scope*

- 1.1 This standard is a compilation of test methods for evaluating properties of thermally conductive electrical insulation sheet materials to be used for dielectric applications.
- 1.2 Such materials are thin, compliant sheets, typically produced by mixing thermally conductive particulate fillers with organic or silicone binders. For added physical strength these materials are often reinforced with a woven or nonwoven fabric or a dielectric film.
- 1.3 These test methods apply to thermally conductive sheet material ranging from about 0.02 to 6-mm thickness.
- 1.4 The values stated in SI units are to be regarded as standard.

Note 1—There is no IEC publication or ISO standard equivalent to this standard.

1.5 This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use. See also 18.1.2 and 19.1.2.

2. Referenced Documents

- 2.1 ASTM Standards:²
- D149 Test Method for Dielectric Breakdown Voltage and Dielectric Strength of Solid Electrical Insulating Materials at Commercial Power Frequencies
- D150 Test Methods for AC Loss Characteristics and Permittivity (Dielectric Constant) of Solid Electrical Insulation
 D257 Test Methods for DC Resistance or Conductance of
- D257 Test Methods for DC Resistance or Conductance of Insulating Materials

- D374M Test Methods for Thickness of Solid Electrical Insulation (Metric)
- D412 Test Methods for Vulcanized Rubber and Thermoplastic Elastomers—Tension
- D624 Test Method for Tear Strength of Conventional Vulcanized Rubber and Thermoplastic Elastomers
- D792 Test Methods for Density and Specific Gravity (Relative Density) of Plastics by Displacement

D883 Terminology Relating to Plastics

- D1000 Test Methods for Pressure-Sensitive Adhesive-Coated Tapes Used for Electrical and Electronic Applications
- D1458 Test Methods for Fully Cured Silicone Rubber-Coated Glass Fabric and Tapes for Electrical Insulation
- D1711 Terminology Relating to Electrical Insulation
- D2240 Test Method for Rubber Property—Durometer Hardness
- D5470 Test Method for Thermal Transmission Properties of Thermally Conductive Electrical Insulation Materials
- D6054 Practice for Conditioning Electrical Insulating Materials for Testing (Withdrawn 2012)³

3. Terminology

- 3.1 Definitions:
- 3.1.1 For definitions of terms used in these test methods and associated with electrical and electronic insulating materials, use Terminology D1711.
- 3.1.2 For definitions of terms used in these test methods and associated with plastics, use Terminology D883.
 - 3.2 Definitions of Terms Specific to This Standard:
- 3.2.1 apparent thermal conductivity, n—the time rate of heat flow, under steady conditions, through unit area, per unit temperature gradient in the direction perpendicular to the area, for a nonhomogeneous material.
- 3.2.1.1 See 16.1 for a discussion of the terms *thermal* conductivity and apparent thermal conductivity. To avoid confusion, these test methods use apparent thermal conductivity for measurements of homogeneous and nonhomogeneous materials.

¹ These test methods are under the jurisdiction of ASTM Committee D09 on Electrical and Electronic Insulating Materials and are the direct responsibility of Subcommittee D09.19 on Dielectric Sheet and Roll Products.

Current edition approved Nov. 1, 2014. Published November 2014. Originally approved in 1998. Last previous edition approved in 2010 as D6343 – 10. DOI: 10.1520/D6343-14.

² For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

³ The last approved version of this historical standard is referenced on www.astm.org.



4. Significance and Use

- 4.1 These test methods are useful to determine compliance of thermally conductive sheet electrical insulation with specification requirements established jointly by a producer and a user.
- 4.2 These test methods have been found useful for quality assessment. Results of the test methods can be useful in apparatus design.

5. Specimen Preparation

5.1 From a sample of sufficient size, prepare test specimens of the dimensions and of the quantity to meet the requirements for each test procedure.

6. Conditioning

- 6.1 Unless otherwise specified, condition specimens in accordance with Procedure A of Practice D6054. Perform all tests on specimens that are in equilibrium with the conditions of Procedure A of Practice D6054. Make the tests in a chamber maintained at $23 \pm 2^{\circ}$ C and 50 ± 5 % relative humidity.
- 6.2 When required by a test procedure, condition specimens in accordance with Procedure D of Practice D6054, except that either distilled or deionized water are permitted to be used. In such cases, remove the specimens from the water into air maintained at 23 \pm 2°C and 50 \pm 5% relative humidity, remove surface water with a paper towel, and begin testing within 30 s.

7. Precision and Bias

7.1 No evaluation of precision or bias has been established for the test methods herein as they relate to these thin thermally conductive materials. For general guidance only, it is suitable to make reference to Precision and Bias statements in the referenced test methods as listed in Section 2.

8. Thickness

- 8.1 Significance and Use—The accurate determination of thickness is essential for design purposes for both thermal conduction and electrical insulation. Thickness enters into the calculation of thermal, electrical, and tensile properties.
 - 8.2 Procedure:
- 8.2.1 Make thickness measurements on specimens in accordance with Test Methods D374M, Method H. This test method uses a micrometer which applies a pressure of 26 \pm 4 kPa on the specimen, using a 6.25-mm diameter presser foot.
- 8.2.2 Clean the surfaces where the measurements are to be made. Take five randomly spaced measurements to cover the length and width of the specimen. Take measurements at least 6 mm from the edges of the specimen.
- Note 2—At the compressive loads of this test method, some materials will undergo compression or compression deflection. It is important for the buyer and seller to agree on other conditions of pressure, anvil and presser foot geometry, and the dwell time to be used.
- 8.3 *Report*—Report the thickness in millimetres as the average of the five measurements.

9. Adhesion Strength


- 9.1 Significance and Use—Materials covered by this test method are optionally coated with a pressure sensitive adhesive on one or both sides. In some cases performance in a particular application can be affected by the adhesion strength.
- 9.2 *Procedure*—Test three specimens of 25-mm width in accordance with Test Methods D1000, except clean the steel panel with isopropyl alcohol.
- 9.3 *Calculation*—From the three specimens, calculate the average adhesion strength.
- 9.4 *Report*—Report the average adhesion strength in newtons per metre of width.

10. Breaking Strength

- 10.1 Significance and Use—In some cases, breaking strength is a significant limitation on methods of applying tapes. Hence, measurements of the tensile force they are able to withstand are potentially important data.
 - 10.2 Procedure:
- 10.2.1 Prepare three specimens at least 500 mm long and 25 mm wide. If the material contains reinforcing fibers, cut the test specimen such that the machine direction reinforcing fibers are parallel to the long axis of the specimen. In the case of materials narrower than 25 mm, test the full width as received.
- 10.2.2 Test the breaking strength in accordance with Test Methods D1458.
- 10.3 *Calculation*—From the test measurements on the three specimens, calculate the average breaking strength.
- 10.4 *Report*—Report the average breaking strength in newtons per metre of width.

11. Tensile Strength and Elongation

- 11.1 Significance and Use—Tensile test results with these materials will vary with specimen geometry and conditions of testing. Hence, these tensile measurements are not always reliable indicators of usefulness in a particular application. Tensile properties of glass-fiber-reinforced materials vary with the ratio of the glass-fiber thickness to the total thickness. Measurements of tensile properties vary with the direction of the glass fibers with respect to the direction in which the specimen is cut.
 - 11.2 Procedure:
- 11.2.1 Prepare three specimens in accordance with Test Methods D412, using Die C.
- 11.2.2 If the material contains reinforcing fibers, cut the test specimen such that any reinforcing fibers are at $45 \pm 10^{\circ}$ to the long axis of the specimen.
- 11.2.3 In accordance with Test Methods D412, measure the tensile breaking strength and tensile elongation at a jaw separation rate of 500 mm/min (20 in./min).
 - 11.3 Calculation:
- 11.3.1 Calculate the tensile strength in kilopascals, using the initial thickness and width for each specimen. Calculate the average tensile strength from the three test measurements.



- 11.3.2 Similarly, calculate each elongation at break as a percentage of the initial jaw separation. Calculate the average from the three test measurements.
- 11.4 *Report*—Report the average tensile strength in kilopascals and the average elongation in percent.

12. Hardness

- 12.1 Significance and Use—This test method is empirical and intended for control purposes only.
 - 12.2 Procedure:
- 12.2.1 Prepare a sufficient number of specimens to form a stack approximately 6 mm high.
- 12.2.2 Determine the indentation hardness in accordance with Test Method D2240, with the following exception:
- 12.2.2.1 Read the scale within 2 s after the presser foot is in firm contact with the specimen.
- 12.3 *Calculation*—From the five measurements taken at different locations on the specimen, calculate the average hardness.
- 12.4 *Report*—Report the average hardness, in accordance with the Shore Hardness system.

13. Specific Gravity

- 13.1 Significance and Use—Specific gravity is a potentially useful tool to help verify proper filler loading and distribution and it is information occasionally required by designers of specific applications of these materials.
- 13.2 *Procedure*—Prepare two specimens of at least 650 mm² in area and test in accordance with Test Methods D792. Method A-1.
- 13.3 *Report*—Report the average of the two test measurements as the specific gravity.

14. Tear Strength

- 14.1 Significance and Use:
- 14.1.1 In certain applications, these materials are stressed during installation in such a way as to introduce tearing stresses on the material. Tear strength measurements provide a means of comparing or specifying materials for such applications.
- 14.1.2 The type of reinforcement, testing rate, and specimen size affect the tear resistance. The results obtained by this test method are predictive of performance only under certain specific conditions of use.
 - 14.2 Procedure:
- 14.2.1 Prepare three specimens using Die C of Test Method D624.
- 14.2.2 If the material contains reinforcing fibers, cut the test specimen such that any reinforcing fibers are at $45 \pm 10^{\circ}$ to the long axis of the specimen (the "A" dimension of Die C).
- 14.2.3 Measure the tear strength in accordance with Test Methods D412, using a jaw separation rate of 500 mm/min (20 in./min).
- 14.3 *Calculation*—Calculate the tear strength for each specimen by dividing the maximum force by the specimen thickness. Calculate the average from the three test measurements.

14.4 *Report*—Report the average tear strength in newtons per millimetre.

15. Thermal Impedance

- 15.1 Significance and Use—Thermal impedance measurements are affected by applied pressure, thickness, any surface irregularities, and uniformity of heat flow. Since the results obtained by these test methods represent thermal characteristics of a material under a specific set of conditions, it is not appropriate to use these results to predict performance in an application where conditions differ from those of the test.
 - 15.2 Procedure:
- 15.2.1 Prepare specimens for two determinations, as required by either Method A or Method B of Test Method D5470.
- 15.2.2 Measure the thermal impedance in accordance with Test Method D5470, using a pressure of 3.0 ± 0.1 MPa and an average specimen temperature of $50 \pm 5^{\circ}$ C.
- 15.3 *Calculation*—From the two determinations, calculate the average thermal impedance.
- 15.4 *Report*—Report the average thermal impedance in $(m^2 \cdot K)/W$ and the test method used.

16. Apparent Thermal Conductivity

- 16.1 Significance and Use—Thermal conductivity applies only to homogeneous materials. Thermally conductive electrically insulating materials are heterogeneous since they typically include ceramic fillers and elastomeric binders, and are often reinforced with glass fiber or a layer of dielectric film. Hence the term apparent thermal conductivity is more appropriate. Because of the multilayer nature of these products, the apparent thermal conductivity will vary with material thickness.
 - 16.2 Procedure:
- 16.2.1 Prepare specimens in accordance with either Method A or Method B of Test Method D5470.
- 16.2.2 In accordance with Test Methods D5470, determine the thermal impedance of layered stacks using 1, 2, and 3 layers of specimens at 3 \pm 0.1-MPa pressure. Use either Test Method A or Test Method B of Test Method D5470.
- 16.3 *Calculation*—Calculate the apparent thermal conductivity from the slope of a plot of thermal impedance against specimen stack thickness.
- 16.4 *Report*—Report the apparent thermal conductivity in W/(m·K) and the test method used.

17. Permittivity and Dissipation Factor

- 17.1 *Significance and Use*—Test Methods D150 discuss the significance of dielectric properties and dissipation factor.
- 17.2 *Procedure*—Prepare four specimens. Use 75-mm diameter conducting paint opposed electrodes. Test each specimen at 1 kHz in accordance with Test Methods D150 in air at a temperature of $23 \pm 2^{\circ}$ C.
- 17.3 *Report*—Report the electrodes used, the individual values, and the average value of permittivity and dissipation factor for the four specimens.

18. Volume Resistivity

18.1 Significance and Use:

18.1.1 Volume resistivity is important in designing an insulator for a specific application. Volume resistivity is affected by humidity and temperature. The extent of change in volume resistivity needs to be considered in developing a design for a specific application.

18.1.2 Warning—Lethal voltages are a potential hazard during the performance of this test. It is essential that the test apparatus, and all associated equipment electrically connected to it, be properly designed and installed for safe operation. Solidly ground all electrically conductive parts which it is possible for a person to contact during the test. Provide means for use at the completion of any test to ground any parts which were at high voltage during the test or have the potential for acquiring an induced charge during the test, or retaining a charge even after disconnection of the voltage source. Thoroughly instruct all operators as to the correct procedures for performing tests safely. When making high voltage tests, particularly in compressed gas or in oil, it is possible for the energy released at breakdown to be sufficient to result in fire, explosion, or rupture of the test chamber. Design test equipment, test chambers, and test specimens so as to minimize the possibility of such occurrences and to eliminate the possibility of personal injury. If the potential for fire exists, have fire suppression equipment available.

18.1.3 See also Significance and Use statement in Test Methods D257.

18.2 Procedure:

18.2.1 Prepare specimens in accordance with Test Methods D257. It is recommended that flat-plate, guarded, and heated electrodes be used. Use electrodes which are satisfactory for electrical resistance measurement on specimens in thermal equilibrium with any specific temperature between 20 and 150°C.

18.2.2 Condition specimens in accordance with Procedure A of Practice D6054.

18.2.3 Condition additional specimens in accordance with Procedure D of Practice D6054. (See also 6.2.)

18.2.4 For each condition, measure the electrical resistance of two specimens at $500 \pm 5\text{-V}$ dc and 60-s electrification time using the procedures of Test Methods D257. Use the thickness as determined in Section 8 for the calculation of electrical resistivity.

18.2.5 If the results of the tests differ by a factor of more than ten, test four additional specimens.

18.3 Calculation:

18.3.1 From the specimens conditioned in accordance with 18.2.2, calculate the median volume resistivity.

18.3.2 From the specimens conditioned in accordance with 18.2.3, calculate the median volume resistivity.

18.4 *Report*—Report the median, maximum, and minimum volume resistivity in ohm-centimetre for each condition.

19. Dielectric Breakdown Voltage

19.1 Significance and Use:

19.1.1 This test method provides useful information as to the suitability of a material for a particular application. Since the conditions under which a dielectric behaves in service often differ from test conditions, the results obtained by this test method are predictive of the performance only under certain specific conditions of use and are not appropriate for applications where conditions differ from those of the test method.

19.1.2 Warning—Lethal voltages are a potential hazard during the performance of this test. It is essential that the test apparatus, and all associated equipment electrically connected to it, be properly designed and installed for safe operation. Solidly ground all electrically conductive parts which it is possible for a person to contact during the test. Provide means for use at the completion of any test to ground any parts which were at high voltage during the test or have the potential for acquiring an induced charge during the test, or retaining a charge even after disconnection of the voltage source. Thoroughly instruct all operators as to the correct procedures for performing tests safely. When making high voltage tests, particularly in compressed gas or in oil, it is possible for the energy released at breakdown to be sufficient to result in fire, explosion, or rupture of the test chamber. Design test equipment, test chambers, and test specimens so as to minimize the possibility of such occurrences and to eliminate the possibility of personal injury. If the potential for fire exists, have fire suppression equipment available.

19.1.3 See also Significance and Use statement in Test Method D149.

19.2 Procedure:

19.2.1 Prepare ten specimens of sufficient size to prevent flashover.

19.2.2 Condition five specimens in accordance with Procedure A of Practice D6054.

19.2.3 Condition the other five specimens in accordance with Procedure D of D6054.

19.2.3.1 Preparatory to testing, remove surface water from each specimen and begin testing within 30 s.

19.2.4 Make breakdown voltage tests and thickness measurements in accordance with Test Method D149, with the following conditions:

19.2.4.1 Test in air at 23 \pm 2°C.

19.2.4.2 Use Type I electrodes of Table 1.

19.2.4.3 Use Method A (Short-Time Test).

19.3 Calculation:

19.3.1 From the five specimens conditioned in accordance with 19.2.2, calculate the average breakdown voltage and average thickness.

19.3.2 From the five specimens conditioned in accordance with 19.2.3, calculate the average breakdown voltage and average thickness.

19.4 *Report*—Report the average, maximum, and minimum breakdown voltage and average thickness for each of the different conditioning procedures.



20. Keywords

20.1 adhesion; apparent thermal conductivity; breakdown voltage; breaking strength; dissipation factor; electrical insula-

tion; hardness; permittivity; thermal conductivity; thermal impedance; thermally conductive; thermally conductive electrical insulation; thin electrical insulation

SUMMARY OF CHANGES

Committee D09 has identified the location of selected changes to this standard since the last issue (D6343 – 10) that may impact the use of this standard. (Approved Nov. 1, 2014.)

(1) Revised Section 3 (Terminology).

ASTM International takes no position respecting the validity of any patent rights asserted in connection with any item mentioned in this standard. Users of this standard are expressly advised that determination of the validity of any such patent rights, and the risk of infringement of such rights, are entirely their own responsibility.

This standard is subject to revision at any time by the responsible technical committee and must be reviewed every five years and if not revised, either reapproved or withdrawn. Your comments are invited either for revision of this standard or for additional standards and should be addressed to ASTM International Headquarters. Your comments will receive careful consideration at a meeting of the responsible technical committee, which you may attend. If you feel that your comments have not received a fair hearing you should make your views known to the ASTM Committee on Standards, at the address shown below.

This standard is copyrighted by ASTM International, 100 Barr Harbor Drive, PO Box C700, West Conshohocken, PA 19428-2959, United States. Individual reprints (single or multiple copies) of this standard may be obtained by contacting ASTM at the above address or at 610-832-9585 (phone), 610-832-9555 (fax), or service@astm.org (e-mail); or through the ASTM website (www.astm.org). Permission rights to photocopy the standard may also be secured from the Copyright Clearance Center, 222 Rosewood Drive, Danvers, MA 01923, Tel: (978) 646-2600; http://www.copyright.com/