

# Standard Practice for Tests to Evaluate the Chemical Resistance of Geonets to Liquids<sup>1</sup>

This standard is issued under the fixed designation D6388; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon  $(\varepsilon)$  indicates an editorial change since the last revision or reapproval.

## 1. Scope

- 1.1 This practice describes procedures for testing geonet products for chemical resistance with liquid wastes, prepared chemical solutions, or leachates, or both, derived from solid wastes.
- 1.2 This practice describes test methods for measuring changes in mass, dimensions, tensile and hydraulic properties and other optional physical and mechanical properties caused by immersion in test solutions, which may be representative of anticipated end use conditions. This practice may be used to assess the extent to which a product's as-manufactured properties are affected by such immersion.
- 1.3 This practice is intended to be used in conjunction with Practices D5322 or D5496. The scope of this practice is limited to testing and reporting procedures for unexposed and exposed geonet samples.
- 1.4 Evaluation or interpretation of test data is beyond the scope of this practice.
- 1.5 This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use. See Section 7 for specific hazards statements.

# 2. Referenced Documents

2.1 ASTM Standards:<sup>2</sup>

D123 Terminology Relating to Textiles

D792 Test Methods for Density and Specific Gravity (Relative Density) of Plastics by Displacement

D1238 Test Method for Melt Flow Rates of Thermoplastics

by Extrusion Plastometer

D1621 Test Method for Compressive Properties of Rigid Cellular Plastics

D4439 Terminology for Geosynthetics

D4595 Test Method for Tensile Properties of Geotextiles by the Wide-Width Strip Method

D4716 Test Method for Determining the (In-plane) Flow Rate per Unit Width and Hydraulic Transmissivity of a Geosynthetic Using a Constant Head

D5035 Test Method for Breaking Force and Elongation of Textile Fabrics (Strip Method)

D5199 Test Method for Measuring the Nominal Thickness of Geosynthetics

D5322 Practice for Laboratory Immersion Procedures for Evaluating the Chemical Resistance of Geosynthetics to Liquids

D5496 Practice for In Field Immersion Testing of Geosynthetics

D5747 Practice for Tests to Evaluate the Chemical Resistance of Geomembranes to Liquids

2.2 EPA Standards:

EPA/600/2–88/052 Lining of Waste Containment and Other Impoundment Facilities<sup>3</sup>

EPA 9090 Compatibility Test for Wastes and Membrane Liners<sup>4</sup>

# 3. Terminology

- 3.1 Definitions:
- 3.1.1 *chemical resistance*, *n for geosynthetics*, the extent to which a material or product retains its original physical and chemical characteristics as a function of immersion in, or contact with, a foreign substance (see Practice D5747).
- 3.1.2 *geonet, n*—a geosynthetic consisting of integrally connected parallel sets of ribs overlying similar sets at various angles for planar drainage of liquids or gases (see Terminology D4439).

 $<sup>^{\</sup>rm 1}$  This practice is under the jurisdiction of ASTM Committee D35 on Geosynthetics and is the direct responsibility of Subcommittee D35.02 on Endurance Properties.

Current edition approved July 1, 2012. Published July 2012. Originally approved in 1999. Last previous edition approved in 2005 as D6388–99(2005). DOI: 10.1520/D6388-99R12.

<sup>&</sup>lt;sup>2</sup> For referenced ASTM standards, visit the ASTM website, www.astm.org, or contact ASTM Customer Service at service@astm.org. For *Annual Book of ASTM Standards* volume information, refer to the standard's Document Summary page on the ASTM website.

<sup>&</sup>lt;sup>3</sup> Available from the *National Technical Information Service*, PB–89–129670.

<sup>&</sup>lt;sup>4</sup> Available from the Superintendent of Documents, U.S. Government Printing Office, Washington, DC 20402.



- 3.1.3 *geosynthetic*, *n*—a planar product manufactured from polymeric material used with soil, rock, earth, or other geotechnical engineering related material as an integral part of a manmade project, structure, or system (see Terminology D4439).
- 3.1.4 *specimen*, *n*—a specific portion of a material or laboratory sample upon which a test is performed or which is taken for that purpose (see Terminology D4439).
- 3.1.5 For definitions of terms used in this practice, refer to Terminologies D123 and D4439.

## 4. Summary of Practice

4.1 This practice defines test methods and procedures for evaluating the resistance of geonet to liquid exposure by monitoring physical and chemical properties of geonet specimens immersed in a test liquid. The physical condition of the geonet is monitored as a function of cumulative exposure time by means of dimensional measurements and physical and chemical property tests.

# 5. Significance and Use

- 5.1 This practice is intended to provide a list of standard procedures for test programs for investigating the chemical resistance of a geonet with a liquid waste, leachate, or chemical. This practice should be used in the absence of other specifications required for the particular situation being addressed.
- 5.2 Chemical resistance, as used in this practice, is not a quantifiable term. This practice is intended to provide a basis of standardization for those wishing to compare or investigate the chemical resistance of a geonet. It should be recognized that chemical resistance is a user judgment evaluation and that this practice does not offer procedures for interpreting the results obtained from test procedures contained herein. As a practice, a test result is not produced.
- 5.3 This practice is for the chemical resistance assessment of geonets and is written in parallel to similar practices for geomembranes, geogrids, geotextiles, and geopipes. Each practice is to be considered individually for the geosynthetic under investigation and collectively for all geosynthetics exposed to the potentially harsh chemical environment under consideration.

#### 6. Apparatus

- 6.1 *Analytical Balance*, capable of weighing to an accuracy of 0.001 g.
- 6.2 *Measuring Equipment*, such as scales or calipers, suitable for determining dimensions of geonet specimens.
- 6.3 All other required equipment is specified in the referenced test methods. Refer to the appropriate standards for a description of the apparatus necessary to perform those tests.

#### 7. Hazards

Note 1—Warning: The solutions used in this practice may contain hazardous chemicals. Appropriate precautions must be taken when handling hazardous waste, chemicals, and the immersion solutions. Protective equipment suitable for the chemicals being used must be worn by all

personnel handling or exposed to the chemicals. Particular care should be taken when opening storage vessels at elevated temperatures due to the increased volatility of organics and the increased activity of acids and bases. Care also must be taken to prevent the spilling of hazardous materials, and provisions must be made to clean up any accidental spills that do occur.

7.1 Before carrying out any test, safety precautions and disposal procedures for hazardous waste, chemicals or immersion solutions, and any contaminated geonet materials, should be identified and implemented to provide full protection to all personnel and to comply with applicable disposal regulations.

# 8. Sampling

8.1 Determine the number and dimensions of the test specimens according to the requirements of the dimensional measurements and physical/polymer property tests to be performed, the duration of the immersion, and the number of test intervals.

Note 2—In contrast to other related chemical resistance test practices, this practice provides for the preparation of individual test specimens directly from roll materials instead of prepared samples or exposure coupons, or both. These test specimens then are used for subsequent exposure and testing.

- 8.2 Sample in accordance with respective test methods selected.
- 8.3 Cut individual test specimens in each the machine and transverse directions from stock roll material.
- 8.4 Mix or shuffle in a random fashion, and then select pre-cut, randomly mixed specimens for assignment to unexposed (baseline) testing or immersion in test solutions for testing after exposure.
- 8.5 Cut individual test specimens for dimension and mass measurements. Specimens may be of any size for which accurate and repeatable measurements can be made, compatible with the immersion tank. Cut specimens from sheet stock using a die to assure consistency of dimensions.

Note 3—Square specimens 152.4 by 152.4 mm (6 by 6 in.) have been found to be satisfactory for dimensional and mass measurements. The same individual specimens may be used for length, width, thickness, and weight change measurements, if desired. Multiple dimensional measurements may be made on a given specimen and averaged to obtain a representative basis for comparison.

# 9. Conditioning

9.1 Condition geonet test specimens at a temperature of 21  $\pm$  2°C (70  $\pm$  4°F) and relative humidity between 50 and 70 % for a period not less than 40 h prior to weighing, or baseline testing and immersion, or a combination thereof.

# 10. Procedure

- 10.1 Immerse the geonet specimens in the test solution as specified in Practices D5322 or D5496.
- 10.2 Immerse a sufficient number of specimens to perform the required testing for each of the immersion periods.
- 10.3 Immerse additional pieces of geonet for dimensional changes and volatile loss for each immersion period. Record the weight of the specimens to an accuracy of at least 0.1~% of

the specimen's weight. Record the thickness of the specimens to an accuracy of 0.0025 mm (0.0001 in.).

- 10.4 Remove a sufficient number of specimens at the prescribed test period for the required testing. Rinse each specimen with deionized water and blot dry with water-absorbent, lint-free towels to remove any visible liquid residue on the specimen surface. Elevated temperature specimens should be allowed to cool to room temperature in a sample of immersion fluid. Specimens should be stored in an airtight container or bag with as little air as possible when not being used or tested in order to minimize moisture, or volatile loss, or both.
- 10.5 The tests to be performed on the geonet specimens are listed in Sections 11 and 12. The tests consist of required testing to be done on the geonet and recommended testing to be performed at the discretion of the user. Recommended tests should be conducted whenever possible as this data will aid in the interpretation of the final test results. All the tests should be completed on the unexposed geonet, as well as the exposed material after each test period. Twice as many specimens as listed below shall be tested on the unexposed material in order to increase precision of baseline data.
- 10.6 Testing (except the extractables test) of the geonet exposed to the test fluid must be done within 24 h of removal from the test solution.

## 11. Required Testing, All Geonets

- 11.1 Weight Change— After each period, remove three preweighed specimens of geonet from the test fluid, quickly blot dry with water-absorbent, lint-free towels to remove any visible liquid residue on the specimen, and weigh to the nearest 0.001 g. Calculate the percent weight change to the nearest 0.1 %.
- 11.2 Dimensional Changes—Measure thickness as directed in Test Method D5199, to the nearest 0.0025 mm (0.0001 in.) at three pre-marked locations on the specimens designated for measurement of weight before and after immersion. Measure length and width (in both machine and transverse directions) at two locations on the geonet specimens designated for dimension testing before and after immersion. Calculate percent changes to the nearest 0.1 %.
- 11.3 Visual Observations—Describe the test specimens before and after immersion. Observations of visual appearance can help in the interpretation of data and may explain anomalous test results. Appearance items to be considered may include a change from original color, as well as, curling, swelling, or other gross specimen changes.
- 11.4 Tensile Properties—Determine tensile properties of unexposed and exposed geonet in accordance with Test Methods D5035. Use specimens 50.8 mm wide by 152.4 mm long (2 by 6 in.), allowing a 50.2-mm (2-in.) gage length with a 50.8 mm (2 in.) wide span. Test at 127 mm/min (5 in./min). Test five samples in each direction (machine and transverse). Determine maximum strength and percent elongation at maximum strength.
- 11.5 Determine hydraulic transmissivity for unexposed and exposed geonet in accordance with Test Method D4716.

- Note 4—The value of test parameters for the transmissivity determination, including hydraulic gradient(s), normal stress(es), and seating time should be specified by the user of this practice.
- 11.6 Determine compressive load/deflection properties of unexposed and exposed geonet in accordance with Test Method D1621, Procedure A. Cut and test three test specimens 150 by 150 mm (6.0 by 6.0 in.). Apply loading at a constant rate of deformation of 1 mm/min (0.04 in./min).
- 11.7 Determine volatiles content of geonet using the procedure in EPA/600/2–88/052, Appendix E.
- 11.8 Determine extractables content of geonet using the procedure in EPA/600/2–88/052, Appendix E.
- 11.9 Determine specific gravity in accordance with Test Methods D792, Method A.

#### 12. Recommended Testing, All Geonets

- 12.1 Wide Width Tensile Properties, modified for testing of geonets—Test geonets using the same procedure required for geotextiles, that is, same specimen size, strain rate, and strength and elongation determinations (see Test Method D4595).
  - 12.2 Melt Index:
- 12.2.1 *Polyethylene*—Use Test Method D1238, Condition 190/2.16.
- 12.2.2 *Polypropylene*—Use Test Method D1238 Condition 230/2.16.

# 13. Report

- 13.1 State that the immersion was performed as directed in Practices D5322 or D5496.
- 13.2 Describe the material or product tested and the material's condition prior to immersion, such as product manufacturer's type and lot number, surface color and gloss, flatness or degree of curl of specimen, estimate of uniformity of channels in x, y, and z planes, degree of angularity or roundness in channel impressions.
- 13.3 Describe the method used to sample the product for the immersion procedure.
- 13.4 Report which test procedures, and any deviations from the procedures, that were used for evaluating the geonet.
  - 13.5 Report all raw data, averages, and standard deviations.
- 13.6 Report the percent changes from the original unexposed test values for the exposed materials.
- Note 5—The test results may be plotted as a function of time of immersion if desired. It is suggested that error bars, range indicators, or similar means to illustrate observed experimental variability be used.
- 13.7 Evaluation or interpretation of test results is beyond the scope of this practice and intended to be done by an appropriate expert.

### 14. Keywords

14.1 chemical resistance; geonets; geosynthetics; liquid wastes

#### **APPENDIXES**

(Nonmandatory Information)

#### X1. TEST SUMMARY

X1.1 Table X1.1 summarizes the testing program outlined in this practice.

**TABLE X1.1 Test Summary** 

Material Property	Test Method
Specific gravity	D792, Method A <sup>A</sup>
Thickness	D5199 <sup>A</sup>
Weight	EPA/600/2-88/052 <sup>A</sup>
Length and width	EPA/600/2-88/052 <sup>A</sup>
Volatile loss	EPA/600/2-88/052, Appendix E <sup>A</sup>
Extractables content	EPA/600/2-88/052, Appendix E <sup>A</sup>
Strip tensile properties	D5035 <sup>A</sup>
Compressive load deflection	D1621 <sup>A</sup>
Transmissivity	D4716 <sup>A</sup>
Wide width tensile properties	D4595 <sup>B</sup>
Melt index	D1238 <sup>B</sup>

A Required testing.

#### **X2. RATIONALE**

X2.1 This practice is intended to provide a standardized procedure for conducting chemical resistance tests for geonet. The term "chemical compatibility" also has been used to describe such tests. The need for this practice was established by ASTM Subcommittee D35.02, with the objective to provide a group of related standards for defining test procedure specifications for chemical resistance studies covering various kinds of geosynthetics. The purpose of such testing is to assess the effects of immersion in liquid waste, leachate, or chemical on geosynthetic materials and products, which will contact the fluids in a waste containment facility. Such testing may be performed as part of the design or regulatory review process.

X2.2 EPA Method 9090 (SW846) has been used widely as a reference describing procedures for chemical resistance

testing of geomembranes. This practice is intended to extend the concept and rationale behind EPA Method 9090 to address geonets. The practice addresses test methods applicable to geonets, and it should be used together with Practice D5322, which defines immersion procedures for geosynthetics in waste fluids.

X2.3 Evaluation or interpretation is beyond the scope of this practice and should be conducted by the owner, or an agent thereof, or an appropriate expert. In general, the facility owner, designer, or geosynthetics user is responsible for defining chemical resistance criteria. Such criteria are generally considered to be site- and application-specific.

ASTM International takes no position respecting the validity of any patent rights asserted in connection with any item mentioned in this standard. Users of this standard are expressly advised that determination of the validity of any such patent rights, and the risk of infringement of such rights, are entirely their own responsibility.

This standard is subject to revision at any time by the responsible technical committee and must be reviewed every five years and if not revised, either reapproved or withdrawn. Your comments are invited either for revision of this standard or for additional standards and should be addressed to ASTM International Headquarters. Your comments will receive careful consideration at a meeting of the responsible technical committee, which you may attend. If you feel that your comments have not received a fair hearing you should make your views known to the ASTM Committee on Standards, at the address shown below.

This standard is copyrighted by ASTM International, 100 Barr Harbor Drive, PO Box C700, West Conshohocken, PA 19428-2959, United States. Individual reprints (single or multiple copies) of this standard may be obtained by contacting ASTM at the above address or at 610-832-9585 (phone), 610-832-9555 (fax), or service@astm.org (e-mail); or through the ASTM website (www.astm.org). Permission rights to photocopy the standard may also be secured from the ASTM website (www.astm.org/COPYRIGHT/).

<sup>&</sup>lt;sup>B</sup> Recommended testing