



Fire-resistance tests — Elements of building construction — Part 9: Specific requirements for non-loadbearing ceiling elements

TECHNICAL CORRIGENDUM 1

Essais de résistance au feu — Éléments de construction —

Partie 9: Exigences spécifiques relatives aux éléments non porteurs de plafond

RECTIFICATIF TECHNIQUE 1

Technical Corrigendum 1 to ISO 834-9:2003 was prepared by Technical Committee ISO/TC 92, *Fire safety*, Subcommittee SC 2, *Fire containment*.

Page 6, 7.1:

Replace the title “**Furnace thermocouples**” with “**Furnace temperature**”.

Page 6, 7.1.1, first sentence:

Delete the first word “Furnace” such that the sentence starts: “Plate thermometers shall be provided (...)”.

Page 6, 7.1.2:

Replace “furnace thermocouples” in the first sentence and “thermocouples” in the second sentence with “plate thermometers” such that the paragraph reads: “The number of plate thermometers shall not be less than one for every 1,5 m² of exposed surface area of the test specimen. There shall be a minimum of four plate thermometers for any test.”