



INTERNATIONAL STANDARD ISO 5599-1:2001
TECHNICAL CORRIGENDUM 1

Published 2007-02-01

INTERNATIONAL ORGANIZATION FOR STANDARDIZATION • МЕЖДУНАРОДНАЯ ОРГАНИЗАЦИЯ ПО СТАНДАРТИЗАЦИИ • ORGANISATION INTERNATIONALE DE NORMALISATION

Pneumatic fluid power — Five-port directional control valves —
Part 1:
Mounting interface surfaces without electrical connector

TECHNICAL CORRIGENDUM 1

Transmissions pneumatiques — Distributeurs à cinq orifices principaux —

Partie 1: Plans de pose sans connecteur électrique

RECTIFICATIF TECHNIQUE 1

Technical Corrigendum 1 to ISO 5599-1:2001 was prepared by Technical Committee ISO/TC 131, *Fluid power systems*, Subcommittee SC 5, *Control products and components*.

Page 1:

Delete the footnote reference “2)” from ISO 1101, the footnote reference “3)” from ISO 1302 and footnotes 2 and 3 at the bottom of the page.

Page 3, Table 1, first row after the header (Size 1), column to the far right-hand side (Orifice area):

Replace the dimension “79” with “70”.

Page 7, Table 3, third column from the left-hand side (Size 1), last row before the footnotes (Orifice area):

Replace the dimension “79” with “70”.

ICS 23.100.50

Ref. No. ISO 5599-1:2001/Cor.1:2007(E)

© ISO 2007 – All rights reserved

Published in Switzerland