

INTERNATIONAL STANDARD

ISO 13919-1

> First edition 1996-08-01

Welding — Electron and laser-beam welded joints — Guidance on quality levels for imperfections —

Part 1: Steel

Soudage — Assemblages soudés par faisceau d'électrons et par faisceau laser — Guide des niveaux de qualité des défauts —

Partie 1: Acier



Reference number ISO 13919-1:1996(E)

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

International Standard ISO 13919-1 was prepared by the European Committee for Standardization (CEN) in collaboration with ISO Technical Committee TC 44, Welding and allied processes, Subcommittee SC 10, Unification of requirements in the field of metal welding, in accordance with the Agreement on technical cooperation between ISO and CEN (Vienna Agreement).

ISO 13919 consists of the following parts, under the general title Welding — Electron and laser beam welding joints — Guidance on quality levels for imperfections:

- Part 1: Steel
- Part 2: Aluminium and its weldable alloys

Annex A of this part of ISO 13919 is for information only.

© ISO 1996

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from the publisher.

International Organization for Standardization
Case postale 56 • CH-1211 Genève 20 • Switzerland
Internet central @isocs.iso.ch
X.400 c=ch; a=400net; p=iso; o=isocs; s=central

Printed in Switzerland

C A O 7 3 7

© ISO

ISO 13919-1:1996(E)

Co	ntents																																										,	Page
Fo	brows											٠.								•															٠.	•					 			iv
Int	roducti	n																												-									•		 			i
1	Scope									٠.							٠.	. .		-											٠.		- •								 			•
2	Norma	tive	ге	fer	en	ce	s														٠.																				 			•
3	Symbo	ols																																		•					 ٠.			•
4	Evalua	tion	01	fw	ele	ds																	٠,									-	- •	•				•			 			•
Δ.	nav A i	info	rm	ativ	vel	Α	do	liti	on	al	in	fo	rı T	na	tic	חמ	f	or	u	SE	9 C	ıf	th	21	S1	tar	nd	ar	ď												 			9

@ ISO

Foreword

The text of EN ISO 13919-1:1996 has been prepared by Technical Committee CEN/TC 121 "Welding", the secretariat of which is held by DS, in collaboration with Technical Committee ISO/TC 44 "Welding and allied processes".

This European Standard is composed of the two following parts:

-Part 1: Steel:

-Part 2: Aluminium and its weldable alloys.

This European Standard shall be given the status of a national standard, either by publication of an identical text or by endorsement, at the latest by February 1997, and conflicting national standards shall be withdrawn at the latest by February 1997.

According to the CEN/CENELEC Internal Regulations, the national standards organizations of the following countries are bound to implement this European Standard: Austria, Belgium, Denmark, Finland, France, Germany, Greece, Iceland, Ireland, Italy, Luxembourg, Netherlands, Norway, Portugal, Spain, Sweden, Switzerland and the United Kingdom.

Introduction

This European standard should be used as a reference in the drafting of application codes and/or for other application standards. It may be used within a total quality system for the production of satisfactory welded joints. It provides three sets of dimensional values from which a selection can be made for a particular application. The quality level necessary in each case should be defined by the application standard or the responsible designer in conjunction with the manufacturer, user and/or other parties concerned. The level shall be prescribed before the start of production, preferably at the inquiry or order stage. For special purposes, additional details may need to be prescribed.

The quality levels given in this standard are intended to provide basic reference data and are not specifically related to any particular application. They refer to welded joints and not the complete product or component itself. It is possible, therefore, for different quality levels to be applied to individual welded joints in the same product or component. Quality levels are listed in table 1.

Table 1: Quality levels for weld imperfections

Level symbol	Quality level
D	Moderate
С	Intermediate
В	Stringent

ISO 13919-1:1996(E)

The three quality levels are arbitrarily identified as D, C and B and are intended to cover the majority of practical applications.

If higher requirements are made on welds than compatible with the above levels (e.g. for dynamic loading) such welds may be machined or ground after welding in order to remove surface imperfections.

It would normally be hoped that for a particular welded joint the dimensional limits for imperfections could all be covered by specifying one quality level. In some cases, however, e.g. for certain types of steels and structures as well as for fatigue loading or leak tightness applications it may be necessary to specify different quality levels for different imperfections in the same welded joint or to include additional requirements.

The choice of quality level for any application should take account of design considerations, subsequent processing, e.g. surfacing, mode of stressing (e.g. static, dynamic), service conditions (e.g. temperature, environment), and consequences of failure. Economic factors are also important and should include not only the cost of welding but also that of inspection, test and repair.

Although this standard includes types of imperfections relevant to the electron and laser beam welding processes, only those which are applicable to the process and application in question need to be considered.

Imperfections are quoted in terms of their actual dimensions, and their detection and evaluation may require the use of one or more methods of non-destructive testing. The detection and sizing of imperfections is dependent on the inspection methods and the extent of testing specified in the application standard or contract.

This standard does not include details of recommended methods of detection and sizing and, therefore, it needs to be supplemented by requirements for examination, inspection and testing. It should be appreciated that methods of non-destructive examination may not be able to give the detection, characterisation and sizing necessary for use within certain types of imperfections shown in table 2.

Although this standard covers a material thicknesses (penetration depths) from 0,5 mm and above for electron and laser beam welding. It should be noted that the permitted size for all types of imperfection has an absolute, upper limit. Application for thicknesses above 50 mm for electron beam welding and 12 mm for laser beam welding is, for that reason, usually safe, but may be overly conservative and may require special precautions, such as weld bead dressing in order to comply with the limits for reinforcement and undercut. Attention should be paid to such precautions during approval testing of the welding procedure and alternative requirements may have to be specified, if necessary.

@ ISO

ISO 13919-1:1996(E)

1 Scope

This standard gives guidance on levels of imperfections in electron and laser beam welded joints in steel. Three levels are given in such a way as to permit application for a wide range of welded fabrications. The levels refer to production quality and not to the fitness-for-purpose of the product manufactured.

This standard applies to electron and laser beam welding of:

- unalloyed and alloyed steels;
- all types of welds welded with or without additional filler wire;
- materials equal to or above 0,5 mm thickness for electron and laser beam welding.

When significant deviations from the joint geometries and dimensions stated in this standard are present in the welded product, it is necessary to evaluate to what extent the provisions of this standard can apply.

Metallurgical aspects, e.g. grain size, hardness are not covered by this standard.

2 Normative references

This European Standard incorporates by dated or undated reference, provisions from other publications. These normative references are cited at the appropriate places in the text and the publications are listed hereafter. For dated references, subsequent amendments to or revisions of any of these publications apply to this European Standard only when incorporated in it by amendment or revision. For undated references the latest edition of the publication referred to applies.

EN 25817

Arc welded joints in steel - Guidance on quality levels for imperfections (ISO 5817:1992)

EN 26520.

Classification of imperfections in metallic fusion welds, with explanations (ISO 6520:1982)

3 Symbols

The following symbols are used in table 2:

- ΔL distance between two imperfections (pore, cavity)
- b width of weld
- d maximum size of an imperfection (pore, cavity)
- f projected areas of pores or cavities
- g distance from centerline in T-joint
- h size of the imperfection (heigth, width)
- h;; h, deviation from the weld penetration
- I length of imperfection (measured in any direction)
- L weld length under consideration (weld length examined)
- Le length of combined porosity (affected weld length)
- s weld penetration
- s, weld penetration in T-joint
- t workpiece thickness

4 Evaluation of welds

Limits for imperfections are given in table 2.

A welded joint should normally be evaluated separately for each individual type of imperfection. Different types of imperfection occurring at any cross-section of the joint may need special consideration.

Table 2: Imperfections

		iso		Limits	for imperfections for qua	lity levels
No	Imperfection, designation	6520 reference	Remarks	moderate D	intermediate C	stringent B
1	Cracks	100	All types of cracks except micro cracks (less than 1 mm ² crack area). For crater cracks see No 2.	not permitted	not permitted	not permitted
2	Crater cracks	104		local crater cracks permitted	not permitted	not permitted
3	Porosity and gas pores	200	The following conditions and limits for imper- factions shall be fulfilled:			
			a) Maximum dimension $\{(I_1, I_2 \text{ or h})\}$ for single pore.	l or h ≤ 0,5 t or 5 mm, whichever is the smaller	I or h ≤ 0,4 t or 3 mm, whichever is the smaller	I or h ≤ 0,3 t or 2 mm, whichever is the smaller
			b) Maximum dimension of the summation of the projected area of the imperfections.	f ≤ 6 %	 f ≤ 2 %	f ≤ 0,7 %
			Projection is in a direction parallel to the surface and perpendicular to the weld axis. It relates to an area t multiplied by weld length, where weld length is the actual length of the weld or 100 mm, whichever is the smaller.			
4	Localised (clustered) and linear porosity	2013 2014	The following conditions and limits for imper- fections shall be fulfilled:			
	meat polosity		a) Maximum dimension $I(I_1, I_2 \text{ or h})$ for single pore.	l or h ≤ 0,5 t or 5 mm, whichever is the smaller	I or h ≤ 0,4 t or 3 mm, whichever is the smaller	I or h ≤ 0,3 t or 2 mm, whichever is the smaller
			b) Maximum dimension of the summation of the projected area of the imperfections.	f ≤ 6 %!	f ≤ 2 %	f ≤ 0,7 %

Table 2 (continued)

		Loc		Limits fo	or imperfections for qual	ity levels
No	Imperfection, designation	ISO 6520 reference	Remarks	moderate D	intermediate C	stringent B
4	Localized (clustered) and linear porosity	2013 2014	Projection is in a direction parallel to the surface and perpendicular to the weld axis. It relates to an area t multiplied by weld length, where weld length is the actual length of the weld or 100 mm, whichever is the smaller. In addition: c) The distances ΔL between the individual pores in clustered or linear porosity shall be assessed. Any two pores closer than: shall be considered a combined porosity. d) Combined porosity is permitted, provided the affected weld length L _c is less than:	0,25 t or 5 mm, whichever is the smaller $L_c \le 2t$	0,5 t or 10 mm, whichever is the smaller $L_c \leq t$	0,5 t or 15 mm, whichever is the smaller $L_c \le t$
L		<u> </u>	Use d) acceptance limit.	<u> </u>	1	<u> </u>

ISO 13919-1:1996(E)

Table 2 (continued)

ISO 13919-1:1996(E)

continued

0

		ISO		Limits for imperfections for quality levels							
Νo	Imperfection, designation	6520 reference	Remarks	moderate D	intermediate C	stringent B					
	Incomplete penetration	402	Welding into backing:								
			Sealing run:								
			Welding of clad materials. Followed by back gouging and arc welding from clad side.								
•	Imperfections specific to fillet welds		Imperfections Nos 10,13,14,15 and 20 according to ISO 5817. Limits for imperfection No 10 according to ISO 5817 depend on the application and shall be specified individually for each particular case.	Use limits for arc welding, see ISO 5817, level D.	Use limits for arc welding, see ISO 5817, level C.	Use limits for arc welding, see ISO 5817, level B.					

Table 2 (continued)

				-	
ity levels	stringent B	h, ≤ 0,1 t + h ₂ or 0,2 t, whichever is the smaller		h ≤ 0,1 t or 0,5 mm, whichever is the smaller	h ≤ 0,1 t or 0,5 mm, whichever is the smaller
Limits for imperfections for quality levels	intermediate C	$h_1 \le 0.2 t + h_2 \text{ or } 0.3 t$, whichever is the smaller		h ≤ 0,2 t or 0,5 mm, whichever is the smaller	h ≤ 0,2 t or 0,5 mm, whichever is the smaller
Limits for	moderate D	$h_1 \le 0,3 t + h_2$ or 0,5 t, whichever is the smaller		h ≤ 0,3 t or 1 mm, whichever is the smaller	h ≤ 0,3 t or 1 mm, whichever is the smaller
	Remarks	- P	The excess penetration may, to some extent, compensate for the sagging. Only for welding of thin plate materials where b ≥ 0,5 t and t ≤ 2 mm.	4	
OSI	6520 reference	509		511	515 5013
		·		<u>≻</u> œ	
	Imperfection, designation	Sagging		Incompletely filled groova	Root concavity Shrinkage groove

continued

Table 2 (concluded)

Limits for imperfections for quality levels moderate intermediate stringent D C	s_1 $t_1 \le 0.15 s_1 or$ $t_2 \le 0.15 s_1 or$ $t_3 \le 0.05 s_2 or$ $t_4 \le 0.15 s_1 or$ $t_4 \le 0.15 s_2 or$ $t_4 \le 0.15 s_3 or$ $t_4 \le 0.15 s_4 or$	Acceptance depends on applications. Spatter is assumed to be of identical composition to the base and filler metals.
Remarks	\$\frac{1}{4}	• 🛱 •
ISO 6520 reference		602
Imperfection, designation	Specified joint axis	Weld spatter
ž	17	18

ISO 13919-1:1996(E)

Annex A (informative)

Additional information for use of this standard

Different parts are very often produced for different applications but to similar requirements. The same requirements should, however, apply to identical parts produced in different workshops to ensure that work is carried out using the same criteria. The consistent application of this standard in one of the fundamental cornerstones of a quality assurance system for use in the production of welded structures.

There is a theoretical possibility of superimposed individual imperfections. In such a case the total summation of all permitted deviations should be restricted by the stipulated values for the different quality levels. However, the value of a single imperfection may exceed Σ h, e.g. for a single pore.

This standard may be used in conjunction with standards for acceptance levels for non-destructive examinations.

© ISO

ICS 25.160.40

Descriptors: welding, steels, electric welding, fusion welding, electron beam welding, welded joints, defects, weld defects, classification, quality classes.

Price based on 9 pages