

INTERNATIONAL STANDARD

ISO 21171

First edition
2006-05-01

Medical gloves — Determination of removable surface powder

*Gants à usage médical — Détermination de la poudre de surface
amovible*



Reference number
ISO 21171:2006(E)

© ISO 2006

PDF disclaimer

This PDF file may contain embedded typefaces. In accordance with Adobe's licensing policy, this file may be printed or viewed but shall not be edited unless the typefaces which are embedded are licensed to and installed on the computer performing the editing. In downloading this file, parties accept therein the responsibility of not infringing Adobe's licensing policy. The ISO Central Secretariat accepts no liability in this area.

Adobe is a trademark of Adobe Systems Incorporated.

Details of the software products used to create this PDF file can be found in the General Info relative to the file; the PDF-creation parameters were optimized for printing. Every care has been taken to ensure that the file is suitable for use by ISO member bodies. In the unlikely event that a problem relating to it is found, please inform the Central Secretariat at the address given below.

© ISO 2006

All rights reserved. Unless otherwise specified, no part of this publication may be reproduced or utilized in any form or by any means, electronic or mechanical, including photocopying and microfilm, without permission in writing from either ISO at the address below or ISO's member body in the country of the requester.

ISO copyright office
Case postale 56 • CH-1211 Geneva 20
Tel. + 41 22 749 01 11
Fax + 41 22 749 09 47
E-mail copyright@iso.org
Web www.iso.org

Published in Switzerland

Contents

Page

Foreword.....	iv
Introduction	v
1 Scope	1
2 Principle	1
3 Terms and definitions.....	1
4 Apparatus	2
5 Reagents	2
6 Sampling	2
7 Method A — Procedure for powdered gloves.....	2
8 Calculation of the result (method A).....	3
9 Methods B and C — Procedure for “powder-free” gloves	3
10 Precision.....	6
11 Test report	8
Bibliography	9

Foreword

ISO (the International Organization for Standardization) is a worldwide federation of national standards bodies (ISO member bodies). The work of preparing International Standards is normally carried out through ISO technical committees. Each member body interested in a subject for which a technical committee has been established has the right to be represented on that committee. International organizations, governmental and non-governmental, in liaison with ISO, also take part in the work. ISO collaborates closely with the International Electrotechnical Commission (IEC) on all matters of electrotechnical standardization.

International Standards are drafted in accordance with the rules given in the ISO/IEC Directives, Part 2.

The main task of technical committees is to prepare International Standards. Draft International Standards adopted by the technical committees are circulated to the member bodies for voting. Publication as an International Standard requires approval by at least 75 % of the member bodies casting a vote.

Attention is drawn to the possibility that some of the elements of this document may be the subject of patent rights. ISO shall not be held responsible for identifying any or all such patent rights.

ISO 21171 was prepared by Technical Committee ISO/TC 45, *Rubber and rubber products*, Subcommittee SC 3, *Raw materials (including latex) for use in the rubber industry*.

This International Standard is based on ASTM D 6124-01, *Standard Test Method for Residual Powder on Medical Gloves*, copyright ASTM, used with permission of ASTM.

For the purposes of this International Standard, the CEN annex regarding fulfilment of European Council Directives has been removed.

Introduction

Depending on their method of manufacture, some medical gloves can have on their surface a small amount of powder, normally modified corn-starch, which is intended to assist donning. Current thinking is that the presence of excessive amounts of such powder can present a health hazard. The methods for the determination of removable surface powder in this International Standard are based on those given in ASTM D 6124-01, from which they differ in the method for determining removable powder from powder-free surgeon's gloves and in the precision data.

Medical gloves — Determination of removable surface powder

WARNING — Persons using this International Standard should be familiar with normal laboratory practice. This standard does not purport to address all of the safety problems, if any, associated with its use. It is the responsibility of the user to establish appropriate safety and health practices and to ensure compliance with any national regulatory conditions.

1 Scope

This International Standard specifies methods for the determination of readily removable powder on the surface of gloves for medical use. Three methods are specified: method A for powdered gloves and methods B and C for powder-free gloves. This International Standard does not address safety issues that may be associated with the presence of powder on gloves nor does it prescribe limits on the amounts that may be present. The applicability of this International Standard to medical gloves not made from rubber has not been established.

2 Principle

The surfaces of a glove are washed with water to remove the water-insoluble powder which is then determined by filtration followed by weighing. The number of gloves used for the procedure depends on whether the gloves are nominally powder-free or powdered.

3 Terms and definitions

For the purposes of this document, the following terms and definitions apply.

3.1

powder

all water-insoluble material on the surface of a glove that is removed by washing under the conditions of the test

3.2

powdered gloves

gloves for which a powder has been used as a part of the manufacturing process, generally to facilitate donning, and described by the manufacturer as “powdered”

3.3

powder-free gloves

gloves which are described by the manufacturer as “powder-free”

NOTE Gloves should always be clearly labelled as to whether they are powdered or powder-free (unlabelled gloves would normally be unacceptable to consumers). Nevertheless, if a sample of gloves does not carry the designation “powdered” or “powder-free”, the gloves should be analysed as if they were powdered.

4 Apparatus

Normal laboratory glassware and tweezers, together with the following:

- 4.1 **Balance**, accurate to 0,1 mg.
- 4.2 **Mechanical shaker**, capable of a minimum oscillation frequency of 1,7 Hz (102 cycles/min).
- 4.3 **Drying oven**, capable of maintaining $100\text{ °C} \pm 5\text{ °C}$.
- 4.4 **Filters**, 90 mm and 47 mm glass microfibre filters of $2,7\text{ }\mu\text{m}$ pore size, together with suction filtration apparatus.
- 4.5 **Desiccator**.

5 Reagents

- 5.1 Wherever water is called for, distilled or deionized water shall be used.

6 Sampling

Randomly select an appropriate number of gloves from each lot to be evaluated. For determinations on powdered gloves, use two gloves and for determinations on powder-free gloves use five gloves *except* in the case of surgeon's gloves for which use three pairs (i.e. six gloves).

7 Method A — Procedure for powdered gloves

- 7.1 Before use, rinse all glassware and tweezers with water.
- 7.2 The test shall be carried out at $25\text{ °C} \pm 5\text{ °C}$ on two gloves randomly selected.
- 7.3 Take a 90 mm, $2,7\text{ }\mu\text{m}$ pore size filter and place it in the desiccator for not less than 30 min. Remove the filter and immediately weigh it on the balance, determining the mass to the nearest 0,1 mg. Record the mass in grams (m_0).

NOTE The use of a PTFE (polytetrafluoroethylene) base is suggested if experience shows that there is a risk of tearing the filter on removal from a glass surface.

- 7.4 Place the filter in the suction apparatus.
- 7.5 Carefully remove a glove from its packaging and insert it into a 1 l capacity conical flask, or other suitable container, containing 500 cm^3 of water so that 1 cm to 3 cm of the cuff projects out round the rim of the flask. Pour approximately 250 cm^3 of water into the glove while holding a small portion of the cuff away from the rim of the flask to allow air to be vented from the flask. While pouring the water into the glove ensure that the projecting part of the cuff is rinsed. Tightly seal the flask with a rubber stopper covered by a small piece of polypropylene sheet so that the flask does not leak. Place the sealed flask in the mechanical shaker and oscillate for 30 s at a speed of not less than 1,7 Hz. Ensure that all the surfaces of the glove are well washed.
- 7.6 Take the flask from the shaker and remove the stopper. Pour the water from inside the glove through the filter in the suction filtration unit. Remove the glove from the flask and pour any remaining water from inside the glove through the filter, followed by the water in the flask.
- 7.7 Using the same glove repeat the procedure of 7.5 and 7.6 with a further 500 cm^3 of fresh water in the flask and 250 cm^3 in the glove.

7.8 Repeat the procedure of 7.7 twice more, to make a total of four fresh water rinses for a single glove. Finally, rinse the flask and stopper covering with fresh water, to ensure that all material on them has been transferred to the filter.

7.9 Using a second glove repeat the procedure of 7.5 to 7.8 (in the case of surgeon's gloves, use the other one of the pair).

7.10 Remove as much water from the filter as possible by suction. Discard the filtrate. Carefully remove the filter and transfer it to a washed and dried watch glass or Petri dish. Dry in an oven at $100\text{ °C} \pm 5\text{ °C}$ for 1 h then transfer to the desiccator to cool for not less than 30 min. Weigh the filter immediately after removal from the desiccator to minimize re-adsorption of moisture. Record the mass, in grams, to the nearest 0,1 mg (m_1).

8 Calculation of the result (method A)

The mass of powder, in milligrams, on the two gloves is given by

$$(m_1 - m_0) \times 1\,000$$

The average mass (m_A) of powder per glove, in milligrams, is given by

$$m_A = \frac{m_1 - m_0}{2} \times 1\,000$$

9 Methods B and C — Procedure for “powder-free” gloves

9.1 General

The procedure to be used for “powder-free” gloves is generally similar to that described above (see Clause 7). However, it employs a smaller filter and five gloves, except in the case of surgeon's gloves when six are used (see the Note) and the same water is used for rinsing each of them. Because only a small amount of powder should be present, it is also necessary to run a blank.

NOTE Surgeon's gloves are packaged in pairs. As the right hand and the left hand are not normally produced at the same time, it is important to test the same number of each hand.

9.2 Method B — Procedure for “powder-free” gloves other than surgeon's gloves

9.2.1 Before use, rinse all glassware and tweezers with water.

9.2.2 The test shall be carried out at $25\text{ °C} \pm 5\text{ °C}$ on five gloves randomly selected.

9.2.3 Take a 47 mm, 2,7 μm pore size filter. Transfer it to the suction apparatus, rinse it with three portions of 50 cm^3 of water and suck free of water. Place the filter on a watch glass or Petri dish and dry it in an oven at $100\text{ °C} \pm 5\text{ °C}$ for 1 h. Transfer the filter to a desiccator to cool for at least 30 min before use. Remove the filter and immediately weigh it on the balance, determining the mass to the nearest 0,1 mg. Record the mass in grams (m_0).

NOTE The use of a PTFE (polytetrafluoroethylene) base is suggested if experience shows that there is a risk of tearing the filter on removal from a glass surface.

9.2.4 Place the filter in the suction apparatus.

9.2.5 Carefully remove a glove from its packaging and insert it into a 1 l capacity conical flask, or other suitable container, containing 500 cm³ of water so that 1 cm to 3 cm of the glove projects out round the rim of the flask. Pour approximately 250 cm³ of water into the glove while holding a small portion of the cuff away from the rim of the flask to allow air to be vented from the flask. While pouring the water into the glove, make sure that the projecting part of the cuff is rinsed. Tightly seal the flask with a rubber stopper covered by a small piece of polypropylene sheet so that the flask does not leak. Place the sealed flask in the mechanical shaker and oscillate for 30 s at a speed of not less than 1,7 Hz. Ensure that all the surfaces of the glove are well washed.

9.2.6 Take the flask from the shaker and remove the stopper. Pour the water inside the glove into a 600 cm³ capacity beaker. Then remove the glove from the flask and pour any water still remaining in the glove into the beaker. Discard the glove.

If any of the water in the conical flask is accidentally transferred at the same time, add water to the flask to maintain the amount at approximately 500 cm³.

9.2.7 Repeat the procedure of 9.2.5 and 9.2.6 using a fresh glove, but leaving the water already present in the flask and using the washing water in the 600 ml beaker to fill the inside of the glove.

9.2.8 Repeat the procedure of 9.2.5 and 9.2.6 for three more gloves, making a total of five.

9.2.9 Pour the water in the 600 cm³ beaker through the suction filter unit containing the weighed filter. Remove the last glove from the flask and pour the remaining water from inside the glove through the filter, followed by the water in the flask. Rinse the beaker, flask and stopper covering with fresh water to ensure that any remaining powder is transferred to the filter.

9.2.10 Remove as much water from the filter as possible by suction. Discard the filtrate. Carefully remove the filter with the tweezers and transfer it to a washed and dried watch glass or Petri dish. Dry in the oven at 100 °C ± 5 °C for 1 h then transfer to the desiccator to cool for not less than 30 min. Weigh the filter immediately after removal from the desiccator to minimize re-adsorption of moisture. Record the mass in grams to the nearest 0,1 mg (m_1).

9.3 Blank determination

Use flasks, stoppers, stopper coverings and a filter and beakers identical to those employed in 9.2.3 and 9.2.4. Determine the mass of the filter (m_F) as described in 9.2.3 and run the procedure described in 9.2.4 to 9.2.6 with 750 cm³ of water as employed for the test but without gloves. After filtering the washings, dry the filter and weigh it as described in 9.2.10. Record the mass (m_B). The mass of any material retained on the filter is given by $m_B - m_F$.

9.4 Calculation of the result (method B)

The mass of powder, in milligrams, on the five gloves is given by:

$$(m_1 - m_0 - m_B + m_F) \times 1\,000$$

The average mass (m_A) of powder, in milligrams, per glove is given by:

$$m_A = (m_1 - m_0 - m_B + m_F) \times 200$$

9.5 Method C — Procedure for “powder-free” surgeon's gloves

The procedure is identical to that of method B other than the total number of gloves.

9.5.1 Before use, rinse all glassware and tweezers with water.

9.5.2 The test shall be carried out at 25 °C ± 5 °C on three pairs of gloves randomly selected.

9.5.3 Take a 47 mm, 2,7 µm pore size filter. Transfer it to the suction apparatus, rinse it with three portions of 50 cm³ of water and suck free of water. Place the filter on a watch glass or Petri dish and dry it in an oven at 100 °C ± 5 °C for 1 h. Transfer the filter to a desiccator to cool for at least 30 min before use. Remove the filter and immediately weigh it on the balance, determining the mass to the nearest 0,1 mg. Record the mass in grams (m_0).

NOTE The use of a PTFE (polytetrafluoroethylene) base is suggested if experience shows that there is a risk of tearing the filter on removal from a glass surface.

9.5.4 Place the filter in the suction apparatus.

9.5.5 Carefully remove a glove from its packaging and insert it into a 1 l capacity conical flask, or other suitable container, containing 500 cm³ of water so that 1 cm to 3 cm of the glove projects out round the rim of the flask. Pour approximately 250 cm³ of water into the glove while holding a small portion of the cuff away from the rim of the flask to allow air to be vented from the flask. While pouring the water into the glove, make sure that the projecting part of the cuff is rinsed. Tightly seal the flask with a rubber stopper covered by a small piece of polypropylene sheet so that the flask does not leak. Place the sealed flask in the mechanical shaker and oscillate for 30 s at a speed of not less than 1,7 Hz. Ensure that all the surfaces of the glove are well washed.

9.5.6 Take the flask from the shaker and remove the stopper. Pour the water inside the glove into a 600 cm³ capacity beaker.

If some of the water in the conical flask is accidentally transferred at the same time, add water to the flask to maintain the amount at approximately 500 cm³.

9.5.7 Repeat the procedure of 9.5.5 and 9.5.6 using the other glove of the pair, but leaving the water already present in the flask and using the washing water in the 600 ml beaker to fill the inside of the glove.

9.5.8 Repeat the procedure of 9.5.5 and 9.5.6 for four more gloves (i.e. two more pairs), making a total of six gloves.

9.5.9 Pour the water in the 600 cm³ beaker through the suction filter unit containing the weighed filter. Remove the last glove from the flask and pour the remaining water from inside the glove through the filter, followed by the water in the flask. Rinse the beaker, flask and stopper covering with fresh water to ensure that any remaining powder is transferred to the filter.

9.5.10 Remove as much water from the filter as possible by suction. Discard the filtrate. Carefully remove the filter with the tweezers and transfer it to a washed and dried watch glass or Petri dish. Dry in the oven at 100 °C ± 5 °C for 1 h then transfer to the desiccator to cool for not less than 30 min. Weigh the filter immediately after removal from the desiccator to minimize re-adsorption of moisture. Record the mass in grams to the nearest 0,1 mg (m_1).

9.6 Blank determination

Use flasks, stoppers, stopper coverings and a filter and beakers identical to those employed in 9.5.3 and 9.5.4. Determine the mass of the filter (m_F) as described in 9.5.3 and run the procedure described in 9.5.4 to 9.5.6 with 750 cm³ of water as employed for the test but without gloves. After filtering the washings, dry the filter and weigh it as described in 9.5.10. Record the mass (m_B). The mass of any material retained on the filter is given by $m_B - m_F$.

9.7 Calculation of the result (method C)

The mass of powder, in milligrams, on the six gloves is given by:

$$(m_1 - m_0 - m_B + m_F) \times 1\,000$$

The average mass (m_A) of powder, in milligrams, per glove is given by:

$$m_A = (m_1 - m_0 - m_B + m_F) \times 166,7$$

10 Precision

10.1 This precision and bias clause has been prepared in accordance with ISO/TR 9272 which may be referred to for terminology and other statistical details.

10.2 The precision details in this precision and bias clause give an estimate of the precision of these test methods with the materials used in the particular interlaboratory programme as described below. The precision parameters should not be used for acceptance/rejection testing of any group of materials without documentation that the parameters are applicable to those particular materials and the specific test protocols that include these test methods.

10.3 A type 1 precision was determined in 2005. Both repeatability and reproducibility are short term. A period of ten days separates replicate test results. The test result is the mean value, as specified by this test method, obtained on two determinations or measurements of the property or parameter in question.

10.4 Four types of powdered glove in method A, three types of powder-free glove in method B and one type of powder-free glove in method C were used in the interlaboratory programme. Testing was performed in 13 laboratories.

10.5 For method A, the procedure for powdered gloves, three replicates of two gloves were used for each glove type.

10.6 For method B, the procedure for powder-free examination gloves, one replicate of five gloves was used for each glove type.

10.7 For method C, the procedure for powder-free surgeon's gloves, one replicate of six gloves (three pairs) was used.

10.8 The results of the precision calculations for repeatability and reproducibility are given in Tables 1, 2 and 3, in descending order of powder average or level, for each of the types of glove evaluated.

10.9 The precision of this test method may be expressed in the format of the following statements that use what is called an "appropriate value" of r , R , (r) or (R) . That is, that value to be used in decisions about test results (obtained with the test method). The appropriate value is that value of r or R associated with a mean level in Tables 1 and 2 closest to the mean level under consideration at any given time, for any given material in routine testing.

10.10 Repeatability: The repeatability, r , of this test method has been established as the most appropriate value tabulated in Tables 1 and 2. Two single test results, obtained under normal test method procedures, that differ by more than this tabulated r (for any given level) shall be considered as derived from different or non-identical sample populations.

10.11 Reproducibility: The reproducibility, R , of this test method has been established as the most appropriate value tabulated in Tables 1 and 2. Two single test results, obtained under normal test method procedures, that differ by more than this tabulated R (for any given level) shall be considered as derived from different or non-identical sample populations.

10.12 Repeatability and reproducibility expressed as a percentage of the mean level, (r) and (R) , have equivalent application statements as above for r and R . For the (r) and (R) statements, the difference in the two single test results is expressed as a percentage of the arithmetic mean of the two test results.

10.13 Bias: In test method terminology, bias is the difference between an average test value and the reference (or true) test property value. Reference values do not exist for this test method since the value (of the test property) is exclusively defined by the test method. Bias, therefore, cannot be determined.

Table 1 — Method A — Procedure for powdered gloves

Type of glove	Average result mg	Within laboratory			Between laboratories		
		s_r	r	(r) %	s_R	R	(R) %
1 Powdered latex, examination	180	7	19	10	15	43	24
2 Powdered latex, surgical	117	10	28	24	14	39	34
3 Powdered synthetic, examination	107	11	31	29	33	93	87
4 Powdered vinyl, examination	26	3	8	30	16	44	165

Table 2 — Method B — Procedure for powder-free examination gloves

Type of glove	Average result mg	Within laboratory			Between laboratories		
		s_r	r	(r) %	s_R	R	(R) %
1 Powder-free latex, examination	0,67	0,12	0,33	49	0,61	1,72	257
2 Powder-free nitrile, examination	0,47	0,14	0,41	87	0,39	1,10	235
3 Powder-free vinyl, examination	0,18	0,08	0,21	115	0,10	0,258	153

Table 3 — Method C — Procedure for powder-free surgeon's gloves

Type of glove	Average result mg	Within laboratory			Between laboratories		
		s_r	r	(r) %	s_R	R	(R) v
1 Powder-free latex, surgical	0,60	0,10	0,29	49	0,44	1,22	205

In Tables 1, 2 and 3

s_r is the repeatability standard deviation, in measurement units;

r is the repeatability, in measurement units ($= 2,8s_r$);

(r) is the repeatability in relative or percentage units;

s_R is the reproducibility standard deviation, in measurement units;

R is the reproducibility in measurement units ($= 2,8s_R$);

(R) is the reproducibility in relative or percentage units.

11 Test report

The test report shall contain the following information:

- a) a reference to this International Standard;
- b) all details necessary for the identification of the gloves tested;
- c) the designation of the gloves as “powdered” or “powder-free”;
- d) whether method A, B or C was used;
- e) the average mass of powder per glove in milligrams;
- f) any unusual features noted during the determination.

Bibliography

- [1] ASTM D 6124-01, *Standard Test Method for Residual Powder on Medical Gloves*
- [2] ISO/TR 9272, *Rubber and rubber products — Determination of precision for test method standards*

ICS 11.140

Price based on 9 pages